

## CMS MOTORHOME INSPECTION FORM

### General Information

Make & Model	Compass Avantgarde 400RI
Reg Number - NO GAP	LV02OVF
HPI Clear	Yes
VAT	No
Engine Size	2.0
BHP	110
Transmission	Manual
Miles or KM	Miles
Mileage	40338
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	
V5 present	Yes

### Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

## CMS MOTORHOME INSPECTION FORM

### Mechanical Inspection

Brake Pedal Pressure Pass?	Yes
Handbrake Test Pass?	Yes
Static Gear Selection Pass?	Yes
Clutch Slip Test Pass?	Yes
Steering Noise	No
Engine noise	No

### Test Drive

Test drive - 10 mins	Pass
Engine Lights	No
Engine Lights Info	
Dashboard Ghosting	N/A
Cruise Control Comment	



## CMS MOTORHOME INSPECTION FORM

### External Inspection

External Extras	Awning, Manual step
Decals	Need attention
Decals Further Info	Faded and cracking in areas
Any Damage Found	Yes
Damage Further Info	Rusting either side of rear nearside wheelarch // Poor repair to paintwork on fuel flap // Paint peel on bonnet // Rust to front & above rear offside wheelarch // N/S/R light cluster cracked // Crease on OSR corner // Crease on habitation door
Windscreen	No damage
Alloy Wheels	N/A
Alloy Wheels Further Info	
Tyres Illegal/Cracking/Out of Date	Yes
Tyre Further Info	Front tyres cracking slightly
Damp Floor Underneath	No
Damp Further Info	
Electric Step	N/A
Self Levelling Work	N/A
Pop Top Canvas Damage	N/A

## CMS MOTORHOME INSPECTION FORM

### Internal Inspection

Internal Look Original	Yes
Berths	4
Belts	2
Bed Options	L Shape Rear, Overcab Bed
Lounge Layout	L-Shaped rear lounge
Layout Correct	Yes
Further Comments	No
Further Comments Info	
Internal Extras	Cab curtains, Carpets, Oven
Other Extras	
Electrics Turn On	Yes
Control Panel Damaged	No
Stereo Turn On	Yes
Smell or Signs of Smoking	No
Cushions Correct	Yes
Boiler Present	Yes
Overhead Lockers Ready	Yes

## CMS MOTORHOME INSPECTION FORM

### Internal Damage & Damp Check

Internal Damage	Yes
Damage Info	Tape around edges of rear skylight // Tape around bathroom vent
Damp Visible/Soft	Yes
Damp Info	Visable damp NS overcab // OS overcab stained // Inside of toilet cassette door soft
Floor Damp/Spongy/Damaged	No
Manuals Present	Yes

### Service History

Engine Service History	Partial
Service Info	
Cam Belt Changed	Yes
Cam Belt Info	Replaced 07/04/10 at 23437 miles
Habitation Service Reports	None
V5 Tested on DVLA	Yes
All Stages Completed	Yes
Completed By	Tim Craner
Sign-off Date	
Price Guide	

## CMS MOTORHOME INSPECTION FORM - PHOTOS

### V5 Document Photos



Photo 1




Photo 2




Photo 3

## CMS MOTORHOME INSPECTION FORM - PHOTOS

### Vehicle VIN Photos



Photo 1



Photo 2

## CMS MOTORHOME INSPECTION FORM - PHOTOS

### External Damage Photos



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8

## CMS MOTORHOME INSPECTION FORM - PHOTOS

### Decal Photos



Photo 1



Photo 2



Photo 3



## CMS MOTORHOME INSPECTION FORM - PHOTOS

### Internal Damage Photos



Photo 1



Photo 2



CMS MOTORHOME INSPECTION FORM - PHOTOS

Cam Belt Invoice Photo




Photo 1

## CMS MOTORHOME INSPECTION FORM - PHOTOS

### Damp Photos



Photo 1



Photo 2