

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Elddis Autoquest 100
Reg Number - NO GAP	PX06CYT
HPI Clear	Yes
VAT	No
Engine Size	2.0
BHP	90
Transmission	Manual
Miles or KM	Miles
Mileage	42176
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	
V5 present	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass?	Yes
Handbrake Test Pass?	Yes
Static Gear Selection Pass?	Yes
Clutch Slip Test Pass?	Yes
Steering Noise	No
Engine noise	No

Test Drive

Test drive - 10 mins	Pass
Engine Lights	No
Engine Lights Info	
Dashboard Ghosting	N/A
Cruise Control Comment	

CMS MOTORHOME INSPECTION FORM

External Inspection

External Extras	Bike Rack, Manual step, Awning
Decals	Need attention
Decals Further Info	Faded on N/S // Overcab decal is torn
Any Damage Found	Yes
Damage Further Info	Scuff on N/S mirror plastic // Rust under passenger door // Dinks on N/S overcab // End cap missing off awning and Awning brackets are very loose// Scrape on N/S overcab wheel arch // Dinks on habitation door and N/S/R end // Damage to rear window //Damage to N/S/R light cluster and a scrape above // Several dinks on rear // Damage to O/S/R top corner // Crazing under front grill
Windscreen	No damage
Alloy Wheels	N/A
Alloy Wheels Further Info	
Tyres Illegal/Cracking/Out of Date	No
Tyre Further Info	
Damp Floor Underneath	No
Damp Further Info	
Electric Step	N/A
Self Levelling Work	N/A
Pop Top Canvas Damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Look Original	Yes
Berths	4
Belts	4
Bed Options	Bench Seats, Overcab Bed
Lounge Layout	Full Dinette, Bench Seats
Layout Correct	Yes
Further Comments	No
Further Comments Info	
Internal Extras	Bluetooth, Cab curtains, Oven
Other Extras	
Electrics Turn On	Yes
Control Panel Damaged	No
Stereo Turn On	Yes
Smell or Signs of Smoking	No
Cushions Correct	Yes
Boiler Present	Yes
Overhead Lockers Ready	Yes

CMS MOTORHOME INSPECTION FORM

Internal Damage & Damp Check

Internal Damage	Yes
Damage Info	Wallpaper coming away on N/S overcab
Damp Visible/Soft	Yes
Damp Info	N/S an O/S overcab has blue staining and pimpling // Staining down the N/S wall next to window // Staining on wall in N/S overhead lockers // Staining on N/S wall under bench seat // Staining and pimpling on O/S wall under window and around dinette // Pimpling next to habitation door // Leisure battery locker door is soft
Floor Damp/Spongy/Damaged	No
Manuals Present	Yes

Service History

Engine Service History	None
Cam Belt Changed	No
Habitation Service Reports	None
V5 Tested on DVLA	Yes
All Stages Completed	Yes
Completed By	Leigh
Sign-off Date	
Price Guide	On

CMS MOTORHOME INSPECTION FORM - PHOTOS

V5 Document Photos



Photo 1



Photo 2



Photo 3

CMS MOTORHOME INSPECTION FORM - PHOTOS

Vehicle VIN Photos



Photo 1



Photo 2

CMS MOTORHOME INSPECTION FORM - PHOTOS

External Damage Photos



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9

CMS MOTORHOME INSPECTION FORM - PHOTOS

Decal Photos



Photo 1



Photo 2



Photo 3

CMS MOTORHOME INSPECTION FORM - PHOTOS

Internal Damage Photos



Photo 1

CMS MOTORHOME INSPECTION FORM - PHOTOS

Damp Photos



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9

Additional 1 photo(s) available in the digital system