

CMS MOTORHOME INSPECTION FORM

General Information

| | |
|------------------------------|---------------------|
| Make & Model | Benimar Tessoro 483 |
| Reg Number - NO GAP | SF68OCN |
| HPI Clear | Yes |
| VAT | Yes |
| Engine Size | 2.0 |
| BHP | 170 |
| Transmission | Automatic |
| Miles or KM | Miles |
| Mileage | 10,000 |
| Confirm miles (within 5,000) | Yes |
| Is Mileage Warranted | Yes |
| Engine Keys Count | |
| V5 present | No |

Engine Bay

| | |
|---------------------------|------|
| Fluid levels correct? | Yes |
| Oil/Coolant Contamination | No |
| Engine bay check | Pass |

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

| | |
|-----------------------------|-----|
| Brake Pedal Pressure Pass? | Yes |
| Handbrake Test Pass? | Yes |
| Static Gear Selection Pass? | Yes |
| Clutch Slip Test Pass? | Yes |
| Steering Noise | No |
| Engine noise | No |

Test Drive

| | |
|------------------------|------|
| Test drive - 10 mins | Pass |
| Engine Lights | No |
| Engine Lights Info | |
| Dashboard Ghosting | No |
| Cruise Control Comment | |

CMS MOTORHOME INSPECTION FORM

External Inspection

| | |
|------------------------------------|--|
| External Extras | Awning, Alloys, Tv Aerial, Habitation door lock, Front fog lights, Solar panel |
| Decals | Good |
| Decals Further Info | |
| Any Damage Found | Yes |
| Damage Further Info | Rear bumper ns cracked // crease in the rear panel // rear bumper os slight damage |
| Windscreen | No damage |
| Alloy Wheels | Good |
| Alloy Wheels Further Info | |
| Tyres Illegal/Cracking/Out of Date | No |
| Tyre Further Info | |
| Damp Floor Underneath | No |
| Damp Further Info | |
| Electric Step | N/A |
| Self Levelling Work | N/A |
| Pop Top Canvas Damage | N/A |

CMS MOTORHOME INSPECTION FORM

Internal Inspection

| | |
|---------------------------|--|
| Internal Look Original | Yes |
| Berths | 4 |
| Belts | 4 |
| Bed Options | Bench Seats, Drop Down Bed |
| Lounge Layout | Half Dinette |
| Layout Correct | Yes |
| Further Comments | No |
| Further Comments Info | |
| Internal Extras | cab A/C, Bluetooth, DAB radio, Sat nav, Multifunction steering wheel, Cab blinds, Cab curtains, Part leather, Oven |
| Other Extras | |
| Electrics Turn On | Yes |
| Control Panel Damaged | No |
| Stereo Turn On | Yes |
| Smell or Signs of Smoking | No |
| Cushions Correct | Yes |
| Boiler Present | Yes |
| Overhead Lockers Ready | Yes |

CMS MOTORHOME INSPECTION FORM

Internal Damage & Damp Check

| | |
|---------------------------|--------------------------------------|
| Internal Damage | Yes |
| Damage Info | Crack os rear panel in the garage // |
| Damp Visible/Soft | No |
| Floor Damp/Spongy/Damaged | No |
| Manuals Present | Yes |

Service History

| | |
|----------------------------|----------------|
| Engine Service History | Partial |
| Service Info | |
| Cam Belt Changed | No |
| Habitation Service Reports | Partial |
| Habitation Info | |
| V5 Tested on DVLA | Yes |
| All Stages Completed | Yes |
| Completed By | Keenan Parnell |
| Sign-off Date | |
| Price Guide | |

CMS MOTORHOME INSPECTION FORM - PHOTOS

External Damage Photos



Photo 1



Photo 2



Photo 3

CMS MOTORHOME INSPECTION FORM - PHOTOS

Internal Damage Photos




Photo 1