

## CMS MOTORHOME INSPECTION FORM

### General Information

Make & Model	Elddis Autoquest 120
Reg Number - NO GAP	HX57RKF
HPI Clear	Yes
VAT	No
Engine Size	2.2
BHP	140
Transmission	Manual
Miles or KM	Miles
Mileage	36552
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	
V5 present	Yes

### Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

## CMS MOTORHOME INSPECTION FORM

### Mechanical Inspection

Brake Pedal Pressure Pass?	Yes
Handbrake Test Pass?	Yes
Static Gear Selection Pass?	Yes
Clutch Slip Test Pass?	Yes
Steering Noise	No
Engine noise	No

### Test Drive

Test drive - 10 mins	Pass
Engine Lights	No
Engine Lights Info	
Dashboard Ghosting	N/A
Cruise Control Comment	

## CMS MOTORHOME INSPECTION FORM

### External Inspection

External Extras	Awning, Reversing camera, Tv Aerial, Bike Rack, Manual step
Decals	Good
Decals Further Info	
Any Damage Found	Yes
Damage Further Info	OSR previous repair
Windscreen	Chip(s) smaller than 10p
Alloy Wheels	N/A
Alloy Wheels Further Info	
Tyres Illegal/Cracking/Out of Date	No
Tyre Further Info	
Damp Floor Underneath	Yes
Damp Further Info	NSR Behind gas locker growing fungus
Electric Step	N/A
Self Levelling Work	N/A
Pop Top Canvas Damage	N/A

## CMS MOTORHOME INSPECTION FORM

### Internal Inspection

Internal Look Original	Yes
Berths	2
Belts	2
Bed Options	U Shape Rear
Lounge Layout	U-Shaped Rear Lounge
Layout Correct	Yes
Further Comments	No
Further Comments Info	
Internal Extras	Oven, Multifunction steering wheel, Cab curtains
Other Extras	
Electrics Turn On	Yes
Control Panel Damaged	No
Stereo Turn On	Yes
Smell or Signs of Smoking	No
Cushions Correct	Yes
Boiler Present	Yes
Overhead Lockers Ready	Yes

## CMS MOTORHOME INSPECTION FORM

### Internal Damage & Damp Check

Internal Damage	Yes
Damage Info	All walls painted magnolia @ kitchen walls wrapped // previous shower tray repair // over boarding on rear wall under seats // box section fitted under NS bench
Damp Visible/Soft	Yes
Damp Info	Staining in bathroom roof
Floor Damp/Spongy/Damaged	Yes
Floor Info	Small area slightly spongy in front of heater
Manuals Present	Yes

### Service History

Engine Service History	Partial
Service Info	
Cam Belt Changed	N/A
Habitation Service Reports	None
V5 Tested on DVLA	Yes
All Stages Completed	Yes
Completed By	Andrew Rowe
Sign-off Date	
Price Guide	

## CMS MOTORHOME INSPECTION FORM - PHOTOS

### V5 Document Photos



Photo 1




Photo 2



Photo 3

## CMS MOTORHOME INSPECTION FORM - PHOTOS

### Vehicle VIN Photos




Photo 1




Photo 2

## CMS MOTORHOME INSPECTION FORM - PHOTOS

### External Damage Photos



Photo 1



## CMS MOTORHOME INSPECTION FORM - PHOTOS

### Windscreen Damage Photos



Photo 1

## CMS MOTORHOME INSPECTION FORM - PHOTOS

### Internal Damage Photos



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7

## CMS MOTORHOME INSPECTION FORM - PHOTOS

### Floor Photos



Photo 1

## CMS MOTORHOME INSPECTION FORM - PHOTOS

### Damp Photos



Photo 1