

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Lunar Roadstar EL
Reg Number - NO GAP	PX18BDE
HPI Clear	Yes
VAT	No
Engine Size	2.3
BHP	0
Transmission	Automatic
Miles or KM	Miles
Mileage	17091
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	
V5 present	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass?	Yes
Handbrake Test Pass?	Yes
Static Gear Selection Pass?	N/A
Clutch Slip Test Pass?	N/A
Steering Noise	No
Engine noise	No

Test Drive

Test drive - 10 mins	Pass
Engine Lights	No
Engine Lights Info	
Dashboard Ghosting	No
Cruise Control Comment	

CMS MOTORHOME INSPECTION FORM

External Inspection

External Extras	Alloys, Awning, Bike Rack, Reversing camera, Tv Aerial, Solar panel, Front fog lights
Decals	Need attention
Decals Further Info	Offside decals peeling
Any Damage Found	Yes
Damage Further Info	Crease above N/S window // N/S/F bumper scuffed // Crease on bonnet // Crack in O/S trim by drivers door // Damage O/S roof // Paint peel O/S/R wheel arch // Crack in O/S/R bumper // Rear trim bulging // Damage to N/S/R bumper corner // Crack in rear window and N/S/R side window // Crack in nearside trim behind passenger door // Paint peel above passenger door on overhead
Windscreen	No damage
Alloy Wheels	Need attention
Alloy Wheels Further Info	Alloys bubbling offside front, nearside rear.
Tyres Illegal/Cracking/Out of Date	Yes
Tyre Further Info	All dated 32/15. Roadworthy.
Damp Floor Underneath	Yes
Damp Further Info	O/S rear corner
Electric Step	N/A
Self Levelling Work	N/A
Pop Top Canvas Damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Look Original	Yes
Berths	2
Belts	2
Bed Options	U Shape Rear
Lounge Layout	U-Shaped Rear Lounge
Layout Correct	Yes
Further Comments	No
Further Comments Info	
Internal Extras	cab A/C, Bluetooth, Cab blinds, Carpets, Cruise control, Multifunction steering wheel, Oven
Other Extras	
Electrics Turn On	Yes
Control Panel Damaged	No
Stereo Turn On	Yes
Smell or Signs of Smoking	No
Cushions Correct	Yes
Boiler Present	Yes
Overhead Lockers Ready	Yes

CMS MOTORHOME INSPECTION FORM

Internal Damage & Damp Check

Internal Damage	Yes
Damage Info	Wallpaper is worn in some of the N/S overhead lockers // Catch broken below oven
Damp Visible/Soft	Yes
Damp Info	O/S wall in cupboard soft
Floor Damp/Spongy/Damaged	No
Manuals Present	Yes

Service History

Engine Service History	Partial
Service Info	
Cam Belt Changed	No
Habitation Service Reports	None
V5 Tested on DVLA	Yes
All Stages Completed	Yes
Completed By	Leigh
Sign-off Date	
Price Guide	On

CMS MOTORHOME INSPECTION FORM - PHOTOS

V5 Document Photos




Photo 1



Photo 2



Photo 3

CMS MOTORHOME INSPECTION FORM - PHOTOS

Vehicle VIN Photos



Photo 1



Photo 2

CMS MOTORHOME INSPECTION FORM - PHOTOS

External Damage Photos



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9

Additional 4 photo(s) available in the digital system

CMS MOTORHOME INSPECTION FORM - PHOTOS

Decal Photos



Photo 1



Photo 2



Photo 3

CMS MOTORHOME INSPECTION FORM - PHOTOS

Alloy Damage Photos



Photo 1

CMS MOTORHOME INSPECTION FORM - PHOTOS

Tyre Photos



Photo 1

CMS MOTORHOME INSPECTION FORM - PHOTOS

Internal Damage Photos



Photo 1



Photo 2

CMS MOTORHOME INSPECTION FORM - PHOTOS

Damp Photos



Photo 1