



Motorhome Inspection Form

General Information

Make & Model	
Reg	
Miles or KM	
Miles/KM	
Transmission	
Engine size	
BHP	
Berths	
Belts	
Lounge	
Bed options	
Further comments	

External Inspection

External Extras	
Any Damage found	
Window damage	
Windscreen	
Alloys	
Garage/lockers	
Further comments	

Internal Inspection

Damp nearside (Visible/soft)	
Damp offside (Visible/soft)	
Damp rear (Visible/soft)	
Damp roof (Visible/soft)	
Damp floor (internal) (Visible/soft)	
Damage	
Internal Extras	
Carpets present	
Are all cushions correct including travel cushions	
Further comments	



Motorhome Inspection Form

Paperwork

V5 present	
Manuals present	
Engine Service Stamps	
Recent Service Date	
Service photo(s)	
Habitation Service reports	



Motorhome Inspection Form

Recent Hab Check Date	
Service photo(s)	



Motorhome Inspection Form

WS Name Glossop Caravans
Address WORKSHOP MAIN A57
BROOKFIELD GLOSSOP
DERBYSHIRE

Job Ref
Customer Code WCHFD013
Customer Mr Mr Worall
Make ELDDIS
Model CHATSWORTH 165

Date
Login to www.approvedworkshops.co.uk and complete the online Customer Satisfaction Survey
Customer Signature
Vin ORD NO 434910
Registration No.

guidance Notes
Moisture levels between 0 and 10% - No cause for concern
Moisture levels between 10 and 20% - May indicate further investigation. Compare with the average moisture level recorded a number of days in the past
Moisture levels between 20 and 25% - May indicate areas possibly requiring remedial work. There may be signs of water ingress or rot/damage of material. Compare with the average readings and consider a record of the date of these reports
Moisture levels between 25 and 30% - Indicates that remedial action is required and remedial action is essential
Moisture levels more than 30% - Indicates that structural damage is possible and remediation is required. Remedial action is necessary

COMMENTS AND RECOMMENDATIONS
All clear

Weather Conditions Wet
Technician Adam brown
Date August 6, 2021

Please Note
We would emphasize that the above report accurately reflects the condition of your Motorhome at the time stated.
These readings may be subject to atmospheric conditions and the company cannot accept any liability for water ingress which may become apparent at a later date.
Compliance with the MCA rules being made and carried out in accordance with the latest AWS Motorhome Standard Working Procedures and repair/retention guidance in relation to areas required to test.
Only the inside of the habitation unit is tested.

Diagrams: Near Side, Off Side, Rear, Front, Ceiling, Floor

Motorhome Habitation Damp Report

Registration No. CHATSWORTH 165
Technician Adam brown
Date August 6, 2021


Diagrams: Floor/Ceiling, Front, Rear, Off Side, Near Side

Notes: The moisture level in the floor is low and the ceiling is low. The moisture level in the front is low and the rear is low. The moisture level in the off side is low and the near side is low.

Logos: Approved Workshop, RAC, AA, AAEP, AAIB, AAIP, AAIR, AAIA, AAII, AAIO, AAII, AAIO, AAII, AAIO



Motorhome Inspection Form



Engine & Drive

Test drive	
Engine lights	
Engine bay check	
Further comments	

Signoff

Completed by	
Date/Time	



Motorhome Inspection Form

In receiving this form you are automatically agreeing with this acknowledgment. Whilst it would be nice to have a full AA style report and professional habitation check, it is not realistic and we are not trained to do so, so take all descriptions & reports as the assessors opinion only. All of our listed checks were opinion of the assessor before the date of the auction, conditions of the motorhome or caravan are expected to change in that time. Take into consideration fair wear and tear for the age of the motorhome. We do not test heating, gas, electric, water systems or accessories. All motorhomes are driven to the auction unless stated. MOT history & mileage checks are public record for the buyer to do their basic due diligence with. This is a trade auction only and must be treated as such. Bidding is bound by British Car Auction terms and conditions. Please visit <https://www.bca.co.uk> for auction terms and conditions. Bid at your own risk.