

#### General

Make & Model       Reg Number (in capitals - no gap)
Reg Number (in capitals - no gap)
HPI Clear
Engine Size
BHP
Transmission
Miles or KM
Mileage
Confirm miles (within 5,000)
Is Mileage Warranted
How many sets of engine keys

#### **External Inspection**

External Extras	
Any Other Extras	
Decals	
Further Info	



Decal Photos	
Any Damage Found	
Windscreen	
Alloy Wheels	
Electric Step	
Does self levelling work? (if applicable)	
Further comments	
Further Photo's	
Further info	
Engine Bay	



Are fluid levels correct? oil/coolant/brake fluid	
More Info	
Engine bay check	
More info	

#### Internal layout

Berths	
Belts	
Lounge	
Bed options	
Layout correct	
Further Comments	
Multi Photo	
Further info	

#### Internal Inspection

Internal Extras	
Other extras	
Do the electrics turn on	
More info	
Control Panel Damaged? Screen/buttons	
More Info	
Does the stereo turn on	
Smell or signs of smoking	
Are all cushions correct including travel cushions	
Is the boiler present	
Are overhead lockers empty/objects secure ready for travel?	
Damage	
Damage info	
Damage photos	
Damp inspection	

Damp (visible/Soft)



Damp info	
Photos of any damp	
Floor damp/spongey/damaged	
Further info	
Floor photos	
Paperwork	
V5 present	
Does the V5 vin match 2 x Vehicle vins	
Manuals present	
Engine service history	
Engine Service info	




Engine Service photos	Сазн		Fleet Care Lt Gavin Fleet Care Ltd Union Park, Triumph Way Wayn Road Industrial Estate Kemption Bedford MK42 708 Tel: 01234 85595 Email: info@gavinfleetcare.co.uk	Ltd	Invoice S12 Date: 08-01-2024 Job:	
	Vehicle	Registration: FV70HHW	-	-	Mileag	e: 8035
	Issues and Work Description	2.3 Diesel - SILVER Work Description CARRY OUT INTERIM SERVICE	- BORSSON		VIN: 2FA25000	002817041
	Work performed	Labour				
	1	Labour MOT Test - (MOT) LABOUR / SERVICE	An cry	Hrs         Unit Price           1.00         54.00           1.00         85.00	VAT % 0.0 20.0 Labour SubTotal	Total 54.00 102.00 £156.00
		Parts Parts OIL OIL FILTER POLLEN FILTER SUMP PLUG WASHER ENV CHARGE SUMDRISK & TOP UPS	Part No	Qty         Unit Price           1.00         75.00           1.00         12.51           1.00         19.50           1.00         1.00           1.00         1.00           1.00         1.50           1.00         4.50	VAT % 20.0 20.0 20.0 20.0 20.0 20.0 20.0 20.	Total 90.00 15.01 23.40 1.20 1.80 5.40
	Invoice Total	VAT         Ket Total         VAT Total           (0)         0.00         54.00         0.00           (1)         20.00         199.01         39.80	-	In	Parts SubTotal Labour Parts VAT voice Total	£136.81 139.00 114.01 39.80 £292.81
		Payment is due within 28 days - Sort Code: 60- Title to the goods supplied remain with this cor upon request Company No. 320 2239 260 - 270 The Village, But	mpany until payment for them has been sa	PAN No. 660 5350 52	& Q.E. Terms & Conditi	ons available Page 1 of 1
Habitation Service Reports						
Habitation service info						



<text></text>	Annual Habitat	ion Service Check	<ul> <li>Done</li> </ul>
<image/> <image/> <image/> <image/> <image/>			
Base Volte/Details         Paging       Protocing		hills	1000.0601/2023 16:36
Pin Pin       Proteom         Discissi Manufature       Pini         Manufature       Pini         Discissi Manufature	Annual Habitation Chec	*	
Original Municipations       Prof.         Machine       Automatical         Datases Number       27.430000201977045         Datases Number       23.556         Datases Number       10.55         Datases Number Num Number Num Number Num Number Number Number Number Number Num Numb	Base Vehicle Details		
Ministering       Aussial         Model Number       215456         Outcomer       0600         Damp Check       1600	075200		
ModelPart Automat Victore Sob Els Holderbin Auto Tradiscipation Discipation<	Contraction of the second s		
Observe Number       27.450000020117011         Number       21.556         Outpot       0630         Damp Check       0630         Damp Report       06300         Damp Report       06300	http://www.com		
Bits Number       21516         Customer       Min Tanang         Damp Check       Image Check         Damp Ch			
Dustorine Mini Taringi   Miningi 0:00     Damp Check   Damp Check   Damp Check   Damp Check   Call Charring Proceedings less them   Af Geo Damp Readings less   Af Geo Damp Read			
Minage       000         Damp Check       Imin         A NG Damp Readings lass film       Imin         Af Gar Damp Readings lass film       Imin         Af Gar Damp Readings lass film       Imin         Af Gar Damp Readings lass       Imin         Af Gar Damp Readi	A to can be been as		
Damp Check         Damp Check      D	10.10		
Damp Chack       Ym         Damp Roport       Anno Robort Roboting leases than Ym         All Charror Robotings lease than Ym       Ym         All Charror Robotings lease than Ym       Ym         All Charror Robotings lease than Ym       Ym         All Edormal Floor Damp Robotings lease than Ym       Ym         All Edormal Floor Damp Robotings lease than Ym       Ym         All Edormal Floor Damp Robotings lease       Ym         Damp Roboting lease       Ym         Mark Heale       0x         Socients       0x         Rob Tree Heaver       0x         Rob Tree I to 1       0x         Rob Tree I to 1       0x		6630	
Damp Check         All NO Damp Readings less that       Ym         All OC Damp Readings less that       Ym         All Roar Damp Readings less that       Ym         All Roar Damp Readings less that       Ym         All External Roar Damp Readings less that       Ym         All External Roar Damp Readings       Ym         All External Roar Damp Readings less that       Ym         All External Roar Damp Readings       Ym         All External Roar Damp Readings less that       Ym         All External Roar Damp Readings       Ym         All External Roar Damp Readings less that       Ym         All External Roar Damp Readings       Ym         All Internal Roar Damp Readings less that       Ym         All Internal Roar Damp Readings less that       Ym         All Internal Roar Damp Readings less that       Ym         Bate than 20%       Ym         Water Heather       NA         Unas Intel       OK         Roar Damp Roar Damp Roar Damp Roadings less that       Ym         Intel Bealt       OK         Roar Damp Roar Damp Roadings less that       Ym         Roar Damp Roadings less that       Ym         Roar Damp Roadings less that       Ym         Roar Damp Roadings less tha			
Damp Report         Al NSD Champ Readings less fram       Ym         Al Colling Data Pleadings less fram       Ym         20%       Ym         20%       Ym         20%       Ym         20%       Ym         20%       Ym         20%       Ym         21%       Ym         21% </td <td>Demp Check</td> <td>Yes</td> <td></td>	Demp Check	Yes	
AV NSD       None         AC CSD Champ Readings less than DNS.       Yms         AC CSD Champ Readings less than DNS.       Yms         AC DSD       Proof Damp Readings less than DNS.       Yms         AL Expense IP Proof Damp Readings less than 2005.       Yms         AL Expense IP Damp Readings less than 2005.       Yms         AL Expense IP Damp Readings less than 2005.       Yms         AL Colling Damp Readings less than 2005.       Yms         Colling Damp Readings less than 2005.       Yms         Colling Damp Readings less toxic       Yms         Colling Damp Readings less toxic       Yms         Colling Damp Readings less toxic       Yms         Colling Camp Readings less toxic       Yms         Colling Camp Readings less toxic       Yms         Colling Readings less toxic       Yms         RCD Test 1 = 1       OK         Damp Readings less toxic       Yms         RCD Test 1 = 1       OK         Damp Readings less toxic       Toxic         Page 1 of 13       OK	Damp Check		
AR, Do Damp Readings less than 20%       Ym         AR, Four Damp Readings less than 20%       Ym         AR box Dotting Readings less than 20%       Ym         Data Phone Readings less than 20%       Ym         Data	Damp Report		
AR, Do Damp Readings less than 20%       Ym         AR, Four Damp Readings less than 20%       Ym         AR box Dotting Readings less than 20%       Ym         Data Phone Readings less than 20%       Ym         Data	All NS Damp Readings less than	Yes	
Af Rear Damp Readings less that Yes         Af Rear Damp Readings less that Yes         All scannel Roor Damp Readings       Yes         Catory K       Ok         Mains Helt       Ok         Rool Teet 1 x 1       Ok         Page 1 of 13       Kes	AE OS Darro Buscinos lass Ban	Van	
20%       Ym         All Internal Floor Damp Readings ima       Ym         All Internal Floor Damp Readings       Ym         Bit Delling Damp Readings ima       Ym	20%	100.7	
All Front Damp Readings intel       Ym         All Johnson Root Damp Readings       Ym         All Internal Floot Damp Readings       Ym         All Colling Damp Readings intel       Ym         Main 2016       Ym         Valuer Header       NA         Utter Header       NA         Onsiger       Oni         Mains Intel       Oni         RCD Teel 1 x 1       Oni         Page 1 of 12       Header	All Rear Damp Readings less than 20%	Yes	
Bash 20%       All Schema Root Dump Readings less lives lives and 20%         All Internal Floor Dump Readings less lives lives and 20%       Yes         All Colling Damp Readings less lives lives and 20%       Yes         All Colling Damp Readings less lives lives and 20%       Yes         All Colling Damp Readings less lives lives and 20%       Yes         All Colling Damp Readings less lives lives and 20%       Yes         Pridge       0%         Valuer Hauter       NA         Uther Heads       0%         Sociatis       0%         Mains Intel       0%         RCD Teel 1 s 1       0%	All Front Damp Readings less	Yes	
Nees that 20%       All Internal Figor Damp Readings       Nal Celling Damp Readings less       Pail Celling Damp Readings less       240 Volt Systems       Fridge     0K       Water Header     NA       Uther Header     0K       Sockets     0K       Charger     0K       Mains Reet     0K       Earth Bonding     0K       RCD Test 1 x 1     0K	than 20%		
Heat than 2015     Yes       All Calling Damp Readings Iees     Yes       240 Volt Systems        Fridge     OK       Water Heatlar     NA       Ultra Heat     OK       Sockets     OK       Obarger     OK       Marins Refet     OK       RCD Test 1 x 1     OK	All External Floor Damp Readings less than 20%	Yas	
All Cabling Damp Readings less than 30%       Ym         240 Volt Systems          Fridge       0K         Water Heater       NA         Uters Heat       0K         Sockets       0K         Despe       0K         RCD Test 1 x 1       0K         Page 1 of 13       0K	All Internal Floor Damp Readings	Yes	
240 Volt Systems         Fridge       OK         Water Header       NuA         Uther Head       OK         Sockets       OK         Charger       OK         Matrix Intel       OK         RCD Text 1 x 1       OK		New 1	
Fridge       OK         Water Header       NVA         Uttra Head       OK         Sockets       OK         Obsrger       OK         Matrix Held       OK         Earth Bonding       OK         RCD Text 1 x 1       OK	than 20%	de l	
Weter Header     NA       Uttra Head     OK       Sockets     OK       Obsrger     OK       Marins Held     OK       RCD Teet 1 x 1     OK	240 Volt Systems		
Utten Heat     0K       Sockets     0K       Obarger     0K       Mains Intel     0K       Earth Bonding     0K       RCD Teat 1 x 1     0K	Fridge	OK	
Sockets     OK       Charger     OK       Mains linket     OK       Earth Bionding     OK       RCD Test 1 x 1     OK	Water Heater	NA.	
Charger OK Mains Intel OK Earth Bonding OK RCD Teal 1 x 1 OK Page 1 of 13	Ultra Heat	OK	
Mains Intel OK Earth Bonding OK RCD Teat 1 x 1 OK Page 1 of 13	Sockets	OK	
Earth Bonding OK RCD Test 1 x 1 OK Page 1 of 13	Charger	OK	
Page 1 of 13	Mains Inlet	OK	
Page 1 of 13	Earth Bonding	OK	
	RCD Test 1 x 1	OK	
			Page 1 of 13
Brownhills	-	72:52 P	
	Annual Marking and		
Annual Machinetics Charts	Annual Habitation Chec	ж	
Annual Habitation Check	RCD Text 1 # 1 Photo		
	Construction of a construction		
Annual Habitation Check RCD Test 1 x 1 Photo		and the second s	
		The star	
	ch (		








Brown	Date Submitted: 06/01/2023 16:36
The UK's Largest Mot	
Annual Habitation Che	JCK
	11 1 CT
12 Volt systems	
Fridge	OK
Fire Ignition	OK
Hob Ignition	OK
Lights Aux Battery Louis	OK
Aux Battery Level Sockets	OK OK
Control Panel	OK
Charging System	OK
Check Fuse Box and Rating	OK
Battery Bones / Venta	OK
USB Ports	OK
Habitation Diesel System	This
Space Heater	NA
Water Heater	NA
Inlet / Exhaust Duct	NA
Fuel Pipe	NA
Gas Systems	
Gas Hose Condition	OK .
Visible Gas Pipes	DK.
Regulator Test Mber Details	Paulty Cap for test point missing
	Page 3 of 13








Brownhills The UK's Largest Motorhome Dealer Annual Habitation Check Pheis	Date Submitted: 06/01/2023 16:36
<ul> <li>Interactive Constraints in the Interaction</li> </ul>	
and the second sec	
Photo State	
Contraction of the	
Fresh Water Gauge / Tap Or:	
Water Dump Valve N/A	
Pump / Pressure Bellch Faulty	
Details Water pump incp, is running bit not flow	
Texted See	
Thefford Seals N/A	
Drain Down System OX Fresh Water Intel Cap OX	
General	
Deer Lock Operation OK	
Roof Vents OK	
	Page 5 of 13








Carevan Door Relainer	tion Service Check	Page 6 of 13
The UK's Largest Mo	torhome Dealer	mitted: 06/01/2023 16:36
Window Stays Extractor Fane	OK N/A	
Metered Tests		
Carbon Monoxide PPM	OK	
Carbon Monoxide PPM Photo		
Aux Batteries Photo		
Browr		Page 7 of 13 mitted: 06/01/2023 16:36
The UK's Largest Mo	torhome Dealer	




	Page 7 of 13
The UK's Largest N Annual Habitation C	lotorhome Dealer
Ges Soundness Test Photo	
Appliances	
Combi Boller Present	No
Space Heater Present	Yas
Make	Whate Sectors
Seriel Number	See photo
Function	Faulty
FFD	ON.
Flue	04
Vent	Ok
Additional Details	Space heater lights on gas, then will go cut before lighting again. This continues writi the heater fails with fault code 1. Inadequate gas supply. Needs further investigation
	Page 8 of 13
	Date Submitted: 06/01/2023 16:36












	Page 10 of 13
	Date Submitted: 06/01/2023 16:36
Annual Habita	ation Check
Oven / Grit Presant	Yes.
Make	Thereford
Model	See photo
Serial Number	See photo
FFD	04
Function	OK
Flue	10
Vert Additional Details	Na
Photo	
Tollet Present	Yes
Muke	Therford
Model	see photo
Serial Number	See photo
Function	OK.
Additional Details	
	Page 11 of 13
The UK's Larg	Date Submitted: 06/01/2023 16:36 gest Motorhome Dealer ation Check







10:15	<b>utl</b> 4G 973
Annual Habitat	ion Service Check 💿 Done
Additional Appliances	2223 No
	Page 12 of 13
Brown The UK's Largest Moto Annual Habitation Cher	orhome Dealer
Service Information / Add	titional Work & Observations
Details	Unable to test water system including water heater due to water pump being inop
Repaired	NA
Photo	
Miscellaneous	(1)
Ges Tank / Bottles Turned Off	No
Roof Lights Latched	Yes
Windows Locked	Yes
All Cupboarde Closed / Latched	Yes
Earth BondChessis	0.025
Continuity Test Gas Drain Down Water System	0.00D Yes
	Yes
12V / Main Power Switch turned Off	
Charger Votage	13.50V
Exterior Lockers Locked	Yes
Exterior Door Looked	Yes
Conclude	
Acknowledgment	Lacknowledge all information recorded on this document is connect to the best of my knowledge.
	Acknowledged
	06/01/2023 12:06
Signature	00012023 12:06
	Destroad 1200
Technicians Name	Oliver Johnson



#### Test drive

Test drive	
Further details	
Engine lights	
Further info	
Dashboard Ghosting	

#### Sign off

Completed by

#### Date/Time

In receiving this form you are automatically agreeing with this acknowledgment. Whilst it would be nice to have a full AA style report and professional habitation check, it is not realistic and we are not trained to do so, so take all descriptions & reports as the assessors opinion only. All of our listed checks were opinion of the assessor before the date of the auction, conditions of the motorhome or caravan are expected to change in that time. Take into consideration fair wear and tear for the age of the motorhome. We do not test heating, gas, electric, water systems or accessories. All motorhomes are driven to the auction unless stated. MOT history & mileage checks are public record for the buyer to do their basic due diligence with. This is a trade auction only and must be treated as such. Bidding is bound by British Car Auction terms and conditions. Please visit https://www.bca.co.uk for auction terms and conditions. Bid at your own risk.