

CMS MOTORHOME INSPECTION FORM

General

CMS Motorhome Inspection	
Make & Model	
Reg Number (in capitals - no gap)	
HPI Clear	
Engine Size	
BHP	
Transmission	
Miles or KM	
Mileage	
Confirm miles (within 5,000)	
Is Mileage Warranted	
How many sets of engine keys	

External Inspection

External Extras	
Any Other Extras	
Decals	
Further Info	
Decal Photos	
Any Damage Found	
Further Information	

CMS MOTORHOME INSPECTION FORM

Damage Photos



CMS MOTORHOME INSPECTION FORM



CMS MOTORHOME INSPECTION FORM

	
Windscreen	
Alloy Wheels	

CMS MOTORHOME INSPECTION FORM

Electric Step	
Does self levelling work? (if applicable)	
Further comments	
Further Photo's	
Further info	

Engine Bay

Are fluid levels correct? oil/coolant/brake fluid	
More Info	
Engine bay check	
More info	


Internal layout

Berths	
Belts	
Lounge	
Bed options	
Layout correct	
Further Comments	
Multi Photo	
Further info	

Internal Inspection

Internal Extras	
Other extras	
Do the electrics turn on	
More info	
Control Panel Damaged? Screen/buttons	
More Info	
Does the stereo turn on	
Smell or signs of smoking	
Are all cushions correct including travel cushions	
Is the boiler present	



CMS MOTORHOME INSPECTION FORM

Are overhead lockers empty/objects secure ready for travel?	
Damage	
Damage info	
Damage photos	



Damp inspection

Damp (visible/Soft)	
Damp info	

CMS MOTORHOME INSPECTION FORM

<p>Photos of any damp</p>	
	
<p>Floor damp/spongey/damaged</p>	
<p>Further info</p>	
<p>Floor photos</p>	
<p>Paperwork</p>	
<p>V5 present</p>	
<p>Does the V5 vin match 2 x Vehicle vins</p>	

CMS MOTORHOME INSPECTION FORM

Manuals present	
Engine service history	
Engine Service info	
Engine Service photos	 <p>01763 252960 sales@mgcaravans.com Mileage: <u>40</u> (Whichever is sooner)</p> <p>First Service - Mechanical</p> <p>Dealer Stamp:  Date: <u>12/10/20</u> Mileage: <u>40915</u> Your next service is due on: Date: <u>12/10/21</u> Mileage: <u>50915</u> (Whichever is sooner)</p> <p>Second Service -</p> <p>Dealer Stamp: <u>Rayment's</u> <u>Small Service See</u> <u>Invoices</u> Date: <u>7.10.22</u> Mileage: <u>42172</u> Your next service is due on: Date: <u>(Brake Fluid)</u> Mileage: <u>changed</u> (Whichever is sooner)</p> <p>Second Service - Mechanical</p> <p>Dealer Stamp: <u>M & W AUTOS (WISBECH) LTD</u> <u>LORDS LANE, WISBECH,</u> <u>CAMBS. PE13 4TU</u> <u>Tel: 01945 410748</u> <u>VAT No. 900 5792 38</u> <u>FULL SERVICE FRONT BRAKE PAID</u> <u>NEW CAM BOLT w/ pump</u> Date: <u>27-9-23</u> Mileage: <u>42962</u> Your next service is due on: Date: Mileage: (Whichever is sooner)</p> <p>17</p>

VOICE

TAX INVOICE NUMBER 19078

TAXPOINT INVOICE DATE 27-9-23

Internal
Warranty

By

PARTS

VAT not Included

Mr.
Fuel
0 ¼ ½ ¾ 1

Warranty Scheme ☒

QTY.	Description	Unit Price	Total Price
1	CAM BELT W/ PUMP KIT		238 65
1	ENGINE MOUNT		125 49
3	BOLTS		13 95
1	OIL FLUSH		8 95
1	OIL FILTER		172 1
1	SEAL		1 60
1	FUEL FILTER		14 50
1	AIR FILTER		26 26
1	POLLIN FILTER		14 75
2	GEAR BOX		20 00
1	SET FRONT PADS		57 30
1	FUEL TREATMENT		11 95
3	ANTI-FREEZE		19 50
	ENVIRO WASTE DISPOSAL		4 00

Hourly Rates

TOTAL PARTS

(LABOUR)

Total Labour and Parts

VAT

VAT Thereon 20 %

Lubricants

VAT Thereon %

D.O.E. Test MOT

VAT Thereon %

Pre-VAT Total

Total VAT

INVOICE TOTAL

Bosch Service Tools Norfolk PE30 1H1

Habitation Service Reports	
Habitation service info	

CMS MOTORHOME INSPECTION FORM

Habitation service photos

MC Caravans
West Chaw, Royston, Hertfordshire, SG8 5HL
01763 259960 - www.mc-caravans.com

Approved Workshop
NCC

AWS Motorhome Habitation Damp Report

Date: 14/11/2024

Customer Signature: [Signature]

Registration Number: VA57 EEN

Guidance Notes

Moisture levels between 0 and 15% - No cause for concern

Moisture levels between 15 and 20% - May require further investigation. Compare with average readings and consider a recheck of the area in three months

Moisture levels between 20 and 25% - Well indicated areas possibly needing remedial work. There may be signs of water ingress or evidence of moisture. Compare with average readings and consider a recheck of the area in three months

Moisture levels between 25 and 30% - Indicates that moisture ingress is occurring and remedial action is necessary

Moisture levels more than 30% - Indicates that structural damage is probable and deterioration inevitable. Remedial action is necessary

Comments and Recommendations

Technician: [Signature]

Date: 14/11/2024

Please Note
We would emphasise that the above report accurately reflects the condition of your Motorhome at the date stated. These readings may be subject to atmospheric conditions and the company cannot accept any liability for water ingress, which may become apparent at a future date.

Completed in line with the NCC damp testing matrix and carried out in accordance with the latest AWS Motorhome Standard Working Procedures and manufacturer's guidance in relation to areas required to test.

Only the inside of the habitation unit is tested.

Moisture Readings Diagram:

- CEILING: 1.2, 1.6, 1.1, 1.6, 1.2, 1.6
- REAR: 1.6, 1.0, 1.2, 1.6, 1.0, 1.2
- FRONT: 1.6, 1.0, 1.2, 1.6, 1.0, 1.2
- OFFSIDE: 1.1, 1.6, 1.1, 1.6, 1.1, 1.6
- NEARSIDE: 1.1, 1.6, 1.1, 1.6, 1.1, 1.6

Test drive

Test drive	
Further details	
Engine lights	
Further info	
Dashboard Ghosting	

Sign off

Completed by	
Date/Time	

CMS MOTORHOME INSPECTION FORM

In receiving this form you are automatically agreeing with this acknowledgment. Whilst it would be nice to have a full AA style report and professional habitation check, it is not realistic and we are not trained to do so, so take all descriptions & reports as the assessors opinion only. All of our listed checks were opinion of the assessor before the date of the auction, conditions of the motorhome or caravan are expected to change in that time. Take into consideration fair wear and tear for the age of the motorhome. We do not test heating, gas, electric, water systems or accessories. All motorhomes are driven to the auction unless stated. MOT history & mileage checks are public record for the buyer to do their basic due diligence with. This is a trade auction only and must be treated as such. Bidding is bound by British Car Auction terms and conditions. Please visit <https://www.bca.co.uk> for auction terms and conditions. Bid at your own risk.