



Motorhome Inspection Form

General Information

Make & Model	
Reg	
Miles or KM	
Miles/KM	
Transmission	
Engine size	
BHP	
Berths	
Belts	
Lounge	
Bed options	
Further comments	

External Inspection

External Extras	
Any Damage found	
Further information	



Motorhome Inspection Form

Damage Photos





Motorhome Inspection Form



Window damage	
Further information	
Multi Photo	
Windscreen	
Alloys	
Garage/lockers	
Further comments	

Internal Inspection

Damp nearside (Visible/soft)	
------------------------------	--



Motorhome Inspection Form

Damp offside (Visible/soft)	
Damp rear (Visible/soft)	
Damp roof (Visible/soft)	
Damp floor (internal) (Visible/soft)	
Damage	
Internal Extras	
Carpets present	
Are all cushions correct including travel cushions	
Further comments	

Paperwork

V5 present	
Manuals present	
Engine Service Stamps	
Recent Service Date	



Motorhome Inspection Form

Service photo(s)

Service photo(s)

Research Garage
Powered by Trust. Driven by You.
www.researchgarage.co.uk

Jeep
Peugeot

Research Garage Peugeot
60 London Road, Hinckley, LE10 1HL
Tel: 01455 437152

Invoice - 402502

Page	1
Invoice	02169197
Date	13/07/2021
PO No.	
IC	F6623
Original	
Type	PRE #DU Retail

Unpaid Cash	475.00	Registration	Model	Milage
		FRL9UK	Van Van	4952
		VIN	Reg Date	Advisor
		ZFA2500002260027	02/08/19	Stobhan Aspley

19 FIAT DUCATO 2.3 35 C/C MULTIJET II DIESEL SEMI AUTO MOTOR CARAVAN SINGLE CAB

Start Date	09/07/21	Done Date	13/07/21
------------	----------	-----------	----------

Code	Description	QTY	Quantity	List	Unit Price	Sell
24	VHC Carry out vehicle health check & video where applicable Vehicle health check carried out. Total Charge for Concern	1				
25	GAS Carry out 30k / 2nd year service - £475.00 Carried Out Service	1	5			194.98
FU1	000007779553 OIL FILTER	1	1	15.06	15.06	15.06
FU1	0000910263930 SEALING GASKET	1	2	3.80	3.80	3.80
FU1	000119663080 FILTERING ELEMENT	1	1	44.82	44.82	44.82
FU1	0000077366607 FILTERING ELEMENT	1	1	47.25	47.25	47.25
FU1	15982716 BRAKE FLUID	1	1	9.45	9.45	9.45
FU1	0000077964063 AIR FILTER	1	1	32.72	32.72	32.72
FU1	0000000070 SCREENWASH	1	1	2.10	2.10	2.10
FU1	001000463M PETRONAS OIL 3L	1	7	8.75	5.95	41.65
	Total Charge for Concern		393.33			

Total Goods	
VAT Due	
Total Due	C/PWD

www.researchgarage.co.uk

Registered Office: 60 London Road, Hinckley, Leicestershire, LE10 1HL
Registered in England No. 1021262 VAT Reg No. GB 113 7792 67

Motability

©2012 Reynolds and Reynolds Limited


Habitation Service reports

Recent Hab Check Date



Motorhome Inspection Form

Service photo(s)





Motorhome Inspection Form

g.sewell@brownhills.co.uk

INVOICE

DALE Motorhome & Caravan Services LTD
 3 Corn Meadows
 Bedworth
 Warwickshire
 CV12 9AS
 dalemc@hotmail.co.uk

Customer Name: MR PARLAND

DALE
 Motorhome & Caravan Services LTD
 07581 036355

Invoice Date: 15/7/2020

Bacs: TSB, 770702, 20103468

Wheel torques should be checked after 20 miles and before every trip

VAT No 291 9294 63

QTY	Description	Line Total
1	<u>FORK HOSE INSPECTION SERVICE</u>	100.00
		VAT 20.00
		Total 120.00

<p>230v consumer unit load test <input checked="" type="checkbox"/></p> <p>230v sockets <input checked="" type="checkbox"/></p> <p>Electric wiring (if fitted) <input checked="" type="checkbox"/></p> <p>Check operation 230v appliances, fans & luminaires <input checked="" type="checkbox"/></p> <p>Check any aftermarket items <input checked="" type="checkbox"/></p> <p>Charge voltage <input checked="" type="checkbox"/></p> <p>Testing Service Technician Name: _____</p> <p>LPG Gas System <input checked="" type="checkbox"/> (Gas appliances not serviced unless requested)</p> <p>Regulator, gas hose, pipework & manifold <input checked="" type="checkbox"/></p> <p>Carry out gas soundness check <input checked="" type="checkbox"/></p> <p>Check security of LPG tank (if fitted) <input checked="" type="checkbox"/></p> <p>Security of gas cylinder(s) <input checked="" type="checkbox"/></p> <p>Ensure all gas dispersal vents are clear <input checked="" type="checkbox"/></p> <p>Appliances - check operation of all gas appliances fitted including FFD's <input checked="" type="checkbox"/></p> <p>Testing Service Technicians Name: _____</p> <p style="font-size: small;">Important - All appliances are tested for operation only. This does not confirm that they are working to the prescribed standard. Additional servicing may be required for warranty purposes/products (e.g. fridge)</p>	<p>Dump test - carry out & note readings on a <input checked="" type="checkbox"/></p> <p>Rising roof (if applicable) <input checked="" type="checkbox"/></p> <p>Ventilation <input checked="" type="checkbox"/> (P F N/A R)</p> <p>Fixed ventilation (low & high levels) <input checked="" type="checkbox"/></p> <p>Roof lights <input checked="" type="checkbox"/></p> <p>Fire & Safety <input checked="" type="checkbox"/> (P F N/A R)</p> <p>Press test button on smoke alarm to test electrical circuitry & sound alarm (if fitted) <input checked="" type="checkbox"/></p> <p>Press test button on CO alarm to test electrical circuitry & sound alarm (if fitted) <input checked="" type="checkbox"/></p> <p>If a fire extinguisher is fitted, check security of its housing (see below) <input checked="" type="checkbox"/></p> <p>Smoke and/or carbon monoxide alarm(s) if fitted:</p> <p>Smoke alarm expiry date (if valid) <u>2029</u></p> <p>Carbon monoxide alarm expiry date (if valid) <u>2029</u></p> <p>Fire extinguisher expiry date <u>2028</u></p>
---	---




Motorhome Inspection Form

of the
 Auto-Trail VR
 nesis Way,
 rth East
 J.

ervice.
 an Auto-Trail
 ct the Auto-Trail
 e which supplied
 natively, details
 rised Auto-Trail
 obtained from
 o-trail.co.uk.

under UK
 e of consumer
 ties do not
 S.




1st SERVICE

Date: 15/7/2019 Mileage: 1589

DALE Motorhome & Caravan Services

Camp Farm, Bedworth Rd, Bulkington, CV12 9JA
 www.dalemcs.co.uk
 Tel: 07581 036355
 Your 2nd service is due on: _____
 or at: or 02476 312057 _____ miles
(whichever is sooner)

Signature: 

2nd SERVICE

Date: _____ Mileage: _____

Your 3rd service is due on: _____
 or at: _____ miles
(whichever is sooner)

Engine & Drive

Test drive	
Engine lights	
Engine bay check	
Further comments	

Signoff

Completed by	
Date/Time	



Motorhome Inspection Form

In receiving this form you are automatically agreeing with this acknowledgment. Whilst it would be nice to have a full AA style report and professional habitation check, it is not realistic and we are not trained to do so, so take all descriptions & reports as the assessors opinion only. All of our listed checks were opinion of the assessor before the date of the auction, conditions of the motorhome or caravan are expected to change in that time. Take into consideration fair wear and tear for the age of the motorhome. We do not test heating, gas, electric, water systems or accessories. All motorhomes are driven to the auction unless stated. MOT history & mileage checks are public record for the buyer to do their basic due diligence with. This is a trade auction only and must be treated as such. Bidding is bound by British Car Auction terms and conditions. Please visit <https://www.bca.co.uk> for auction terms and conditions. Bid at your own risk.