

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Elddis Prestige 105
Reg Number - NO GAP	DG71TVN
HPI Clear	Yes
VAT	No
Engine Size	2.2
BHP	140
Transmission	Manual
Miles or KM	Miles
Mileage	15139
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	
Engine Keys Count	
V5 present	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass?	Yes
Handbrake Test Pass?	Yes
Static Gear Selection Pass?	Yes
Clutch Slip Test Pass?	Yes
Steering Noise	No
Engine noise	No

Test Drive

Test drive - 10 mins	Pass
Engine Lights	No
Engine Lights Info	
Dashboard Ghosting	No
Cruise Control Comment	

CMS MOTORHOME INSPECTION FORM

External Inspection

External Extras	Alloys, Awning, Bike Rack, Reversing camera, BBQ point, Tv Aerial, Solar panel
Decals	Good
Decals Further Info	
Any Damage Found	Yes
Damage Further Info	3 small scratches around OSR light
Windscreen	No damage
Alloy Wheels	Good
Alloy Wheels Further Info	
Tyres Illegal/Cracking/Out of Date	No
Tyre Further Info	
Damp Floor Underneath	No
Damp Further Info	
Electric Step	N/A
Self Levelling Work	N/A
Pop Top Canvas Damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Look Original	Yes
Berths	2
Belts	2
Bed Options	Bench Seats
Lounge Layout	Bench Seats
Layout Correct	Yes
Further Comments	No
Further Comments Info	
Internal Extras	Auto headlights, Bluetooth, Cab blinds, Carpets, cab A/C, Cruise control, DAB radio, Oven
Other Extras	
Electrics Turn On	Yes
Control Panel Damaged	No
Stereo Turn On	Yes
Smell or Signs of Smoking	No
Cushions Correct	Yes
Boiler Present	Yes
Overhead Lockers Ready	Yes

CMS MOTORHOME INSPECTION FORM

Internal Damage & Damp Check

Internal Damage	No
Damp Visible/Soft	No
Floor Damp/Spongy/Damaged	No
Manuals Present	Yes

Service History

Engine Service History	Partial
Service Info	
Cam Belt Changed	N/A
Habitation Service Reports	Full
Habitation Info	
V5 Tested on DVLA	Yes
All Stages Completed	Yes
Completed By	Andrew Rowe
Sign-off Date	
Price Guide	Off

CMS MOTORHOME INSPECTION FORM - PHOTOS

V5 Document Photos




Photo 1




Photo 2




Photo 3

CMS MOTORHOME INSPECTION FORM - PHOTOS

Vehicle VIN Photos



Photo 1



Photo 2



Photo 3

CMS MOTORHOME INSPECTION FORM - PHOTOS

External Damage Photos



Photo 1