


General

CMS Motorhome Inspection	
Make & Model	
Reg Number (in capitals - no gap)	
HPI Clear	
Engine Size	
BHP	
Transmission	
Miles or KM	
Mileage	
Confirm miles (within 5,000)	
Is Mileage Warranted	
How many sets of engine keys	


External Inspection

External Extras	
Any Other Extras	
Decals	
Further Info	




































































Windscreen



Electric Step	
Does self levelling work? (if applicable)	
Further comments	
Further Photo's	
Further info	

Engine Bay

Are fluid levels correct? oil/coolant/brake fluid	
More Info	
Engine bay check	
More info	

Internal layout

Berths	
Belts	
Lounge	
Bed options	
Layout correct	
Further Comments	
Multi Photo	
Further info	


Internal Inspection

Internal Extras	
Other extras	
Do the electrics turn on	
More info	
Control Panel Damaged? Screen/buttons	
More Info	
Does the stereo turn on	
Smell or signs of smoking	
Are all cushions correct including travel cushions	
Is the boiler present	




Are overhead lockers empty/objects secure ready for travel?	
Damage	
Damage info	
Damage photos	













Damp inspection


Damp (visible/Soft)	
Damp info	
Photos of any damp	
Floor damp/spongey/damaged	
Further info	
Floor photos	
Paperwork	

V5 present



Does the V5 vin match 2 x Vehicle vins		
Manuals present		
Engine service history		
Engine Service info		
Engine Service photos	RECORD OF UPKEE	
	BUT YEAR SETEVICE + AIRCON ALL BRAKE DISCS/PADS. LUSURE BATTERY. 6 NEW TYRE'S Dealer'S Stamp Date: 28-5-21 30557 miles	7th Year SERVICE BENYear AIRCON 26/8/22 OSREAR HUB OIL SEAL 5/30 DURA PROSULUS Date: 29-6-72 32-692 MILES
	Sth Year Dealer's Stamp	10th Year 11th Year Dealer's Stamp
	NEW STARTER MOTOR TOIL	Date: Da





















Habitation service photos		
	Motorhome Damp Report <u>man manual states</u> <u>man man man manual states</u> <u>man man man man man man man man man man </u>	Habcheck Mage Bart Markey Martin Markey Martin
	Manking winner SAM. Wat shared were provide reacting works of well. There are the react of an and the source of th	a a data
	Lander - Statement Lander	MMM INDUCIDE I LANS M
	Martin Manager Laws	Der Anscher Lines
	Hor ADDATED LINES	Colling: 2019/2014 11:06:14 added. These makings may be subject to atmospheric conditions, and the
Toot drive		

Test drive

Test drive	
Further details	
Engine lights	
Further info	
Dashboard Ghosting	

Sign off

Completed by	
Date/Time	



In receiving this form you are automatically agreeing with this acknowledgment. Whilst it would be nice to have a full AA style report and professional habitation check, it is not realistic and we are not trained to do so, so take all descriptions & reports as the assessors opinion only. All of our listed checks were opinion of the assessor before the date of the auction, conditions of the motorhome or caravan are expected to change in that time. Take into consideration fair wear and tear for the age of the motorhome. We do not test heating, gas, electric, water systems or accessories. All motorhomes are driven to the auction unless stated. MOT history & mileage checks are public record for the buyer to do their basic due diligence with. This is a trade auction only and must be treated as such. Bidding is bound by British Car Auction terms and conditions. Please visit https://www.bca.co.uk for auction terms and conditions. Bid at your own risk.