

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Bailey Autograph 79-6
Reg Number - NO GAP	FG17MXU
HPI Clear	Yes
VAT	Yes
Engine Size	2.0
BHP	160
Transmission	Manual
Miles or KM	Miles
Mileage	25553
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	
V5 present	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass?	Yes
Handbrake Test Pass?	Yes
Static Gear Selection Pass?	Yes
Clutch Slip Test Pass?	Yes
Steering Noise	No
Engine noise	No

Test Drive

Test drive - 10 mins	Pass
Engine Lights	No
Engine Lights Info	
Dashboard Ghosting	No
Cruise Control Comment	

CMS MOTORHOME INSPECTION FORM

External Inspection

External Extras	Awning, Alloys, Habitation door lock, BBQ point, Reversing camera, Bike Rack, Solar panel, Tv Aerial
Decals	Need attention
Decals Further Info	Slightly faded ns //
Any Damage Found	Yes
Damage Further Info	Slight scratch down ns // crack and silicone under hab door // slight crack ns rear // paint peel os rear // scratch lower os // scratch ns locker door //
Windscreen	No damage
Alloy Wheels	Need attention
Alloy Wheels Further Info	Ns rear oxidation // os rear oxidation //
Tyres Illegal/Cracking/Out of Date	Yes
Tyre Further Info	Ns front slight cracking // os front slight cracking //
Damp Floor Underneath	
Damp Further Info	
Electric Step	N/A
Self Levelling Work	N/A
Pop Top Canvas Damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Look Original	Yes
Berths	6
Belts	6
Bed Options	Drop Down Bed, U Shape Rear, Bench Seats
Lounge Layout	Full Dinette
Layout Correct	Yes
Further Comments	No
Further Comments Info	
Internal Extras	Alarm, cab A/C, Bluetooth, Carpets, Cab blinds, Sat nav, tracker, Oven, Part leather, Multifunction steering wheel
Other Extras	
Electrics Turn On	Yes
Control Panel Damaged	No
Stereo Turn On	Yes
Smell or Signs of Smoking	No
Cushions Correct	Yes
Boiler Present	Yes
Overhead Lockers Ready	Yes

CMS MOTORHOME INSPECTION FORM

Internal Damage & Damp Check

Internal Damage	No
Damp Visible/Soft	No
Floor Damp/Spongy/Damaged	Yes
Floor Info	Os rear under lounge seat soft floor
Manuals Present	Yes

Service History

Engine Service History	Full
Service Info	
Cam Belt Changed	No
Habitation Service Reports	Full
Habitation Info	
V5 Tested on DVLA	Yes
All Stages Completed	Yes
Completed By	Keenan Parnell
Sign-off Date	
Price Guide	

CMS MOTORHOME INSPECTION FORM - PHOTOS

V5 Document Photos




Photo 1




Photo 2




Photo 3

CMS MOTORHOME INSPECTION FORM - PHOTOS

Vehicle VIN Photos



Photo 1



Photo 2

CMS MOTORHOME INSPECTION FORM - PHOTOS

External Damage Photos



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7

CMS MOTORHOME INSPECTION FORM - PHOTOS

Decal Photos



Photo 1

CMS MOTORHOME INSPECTION FORM - PHOTOS

Alloy Damage Photos



Photo 1



Photo 2

CMS MOTORHOME INSPECTION FORM - PHOTOS

Tyre Photos



Photo 1



Photo 2

CMS MOTORHOME INSPECTION FORM - PHOTOS

Floor Photos




Photo 1