

CMS MOTORHOME INSPECTION FORM

General

CMS Motorhome Inspection	
Make & Model	
Reg Number - NO GAP	
HPI Clear	
VAT	
Engine Size	
BHP	
Transmission	
Miles or KM	
Mileage	
Confirm miles (within 5,000)	
Is Mileage Warranted	
How many sets of engine keys	
V5 present	
Does the V5 vin match 2 x Vehicle vins	

Engine Bay

Are fluid levels correct? oil/coolant/brake fluid	
More Info	
Oil/Coolant Contamination	
More Info	
Engine bay check	
More info	

Mechanical Inspection

Brake Pedal Pressure Pass?	
More Info	
Handbrake Test Pass?	
More info	
Static Gear Selection (engine running) Pass?	
More info	
Clutch Slip Test Pass?	

CMS MOTORHOME INSPECTION FORM

More Info	
Steering Noise	
More Info	
Engine noise	
More info	
Video of engine running	

External Inspection


External Extras	
Any Other Extras	
Decals	
Further Info	

CMS MOTORHOME INSPECTION FORM

Decal Photos



CMS MOTORHOME INSPECTION FORM


	
Any Damage Found	
Windscreen	
Damage Photos	
Alloy Wheels	
Further Information	
Damage Photos	
Are the tyres illegal, cracking or out of date (6 years)	
Further Info	

CMS MOTORHOME INSPECTION FORM

Tyre photos



CMS MOTORHOME INSPECTION FORM

	
Electric Step	
Does self levelling work? (if applicable)	
Any damage to the pop top canvas?	
Pop top photos	
Further comments	

CMS MOTORHOME INSPECTION FORM

Further Photo's

keep an eye on your vehicles
PHANTOM
TRACKING SYSTEMS AND SECURITY

Order Line

Account No.	Document Number	Order Number	Date & Tax Point	Created By	Created Date
c0502	53803222		08/01/2025	Zacson Jose	02/01/2025

Make & Model	Reg No.	Reg Date	Mileage In	Mileage Out
Ford Chausson Titanium 628 Aut	GN19CNY	13/04/2019	14180	14180

Chassis No.	Engine No.	Vehicle No.	W.I.P. No.	Job No.
	YNF6JG89439	70173	18273	2751

Description of Goods / Services	Qty.	Unit Price	Unit	Net Total	V
INVESTIGATION.					
A INV				376.61	S
CUSTOMER STATES VEHICLE NON-RUNNER. NO SPEED. NO PWER, JUDDERING ETC. VEHICLE TO BE RECOVERED IN BY AA.					
X F2675955 NOZZLE AND HOLDER -	0062.0	4.00	224.49	224.49 EACH	0.00
X F2011882 CLAMP	0062.0	2.00	3.61	3.61 EACH	5.00
X F2011883 CLAMP	0062.0	2.00	3.59	3.59 EACH	4.00
X F2215510 TUBE ASSY - FUEL	0062.0	1.00	13.06	13.06 EACH	3.00
X F2215508 TUBE ASSY - FUEL	0062.0	2.00	13.06	13.06 EACH	9.00
X F2215506 TUBE ASSY - FUEL	0062.0	1.00	13.06	13.06 EACH	0.00
X F2011881 BOLT	0062.0	4.00	1.39	1.39 EACH	1.00
X F2011992 COVER	0062.0	1.00	31.41	31.40 EACH	0.00
A 29099381MUA	0062.0				8.98
External Power Supply - Connection - All					
A 29099081MUA	0062.0				26.95
Diagnostic Tool Connection/Comm. - All					
A 23482181H7F	0062.0				71.85
R&I Injector Delivery Pipe (One) - 2.0L EcoBlue - Stage 6 with 8F55					
A 23482581MUA	0062.0				8.98
R&I Fuel Inj. Deliv.Tube (Ad. 2.) - All					
A 23482681MUA	0062.0				8.98
R&I Fuel Inj. Deliv.Tube (Ad. 3.) - All					
A 23482781MUA	0062.0				8.98
V	Rate	Service/Goods	VAT	Continued Over Leaf	

Bank Details: Sort Code: 80-80-08 Account No: 00031585 - Natwest.
23 Ashford Road, Maidstone, Kent ME14 5DQ. Tel: 01622 756781. Accounts Tel: 01622 625502
Wealdminster Rd, Canterbury CT1 1YJ. Tel: 01227 931402
73-74 Ellingham Industrial Centre, Ashford, Kent TN23 6JG. Tel: 01233 667929
www.hopnagroup.co.uk
Registered Office: Hopnag Bros Ltd 23 Ashford Road, Maidstone, Kent ME14 5DQ. Registered Office No: 4885. VAT No: 06 223 0649-01

Further info

Internal layout

Berths	
Belts	
Lounge	
Bed options	
Layout correct	
Further Comments	
Multi Photo	

CMS MOTORHOME INSPECTION FORM

Further info	
--------------	--

Internal Inspection

Internal Extras	
Other extras	
Do the electrics turn on	
More info	
Control Panel Damaged? Screen/buttons	
More Info	
Does the stereo turn on	
Smell or signs of smoking	
Are all cushions correct including travel cushions	
Is the boiler present	
Are overhead lockers empty/objects secure ready for travel?	
Damage	
Damage info	


CMS MOTORHOME INSPECTION FORM

Damage photos

Damp inspection

Damp (visible/Soft)	
Damp info	

CMS MOTORHOME INSPECTION FORM


Photos of any damp	
Floor damp/spongey/damaged	
Further info	
Floor photos	

Paperwork

Manuals present	
Engine Service History	
Engine Service info	

CMS MOTORHOME INSPECTION FORM

Engine Service photos



Has the cam belt been changed?
(5 years on all ford 2.0 and fiat
2.3)

Cam belt change info

Cam belt change invoice

Habitation Service Reports

Habitation service info

CMS MOTORHOME INSPECTION FORM

Habitation service photos

APPROVED WORKSHOP
ncc

Motorhome Annual Habitation Service Check Sheet

All work must be carried out in accordance with the latest AWS Standard Working Procedures

Inspector: Please ensure that every question is answered correctly using: P (pass), F (fail), N/A (not applicable) & R (rectified)

Refer to manufacturers guidance

Approved Workshop Name & Address

Job Reference/Date

Make & Model: **628 TITAN** Vln Number: **GN19 CNY**

	P	F	N/A	R
Corner steadies (where applicable)			✓	
Folding steps (where applicable)				
Under slung tanks & pipes	✓			

Electrical System (Technicians Handbook Section 3)

	P	F	N/A	R
230V & 12V fridge operation	✓			
Letsure battery (if fitted)	✓			
Interior lighting & equipment	✓			
Check fuse box & rating	✓			
Awning light	✓			
Wiring on all ELV circuits (visual)	✓			
LV Inlet plug & extension lead	✓			
Earth bonding continuity test	✓			
230V consumer unit load test	✓			
230V sockets	✓			
Electric awning (if fitted)			✓	
Check operation 230V appliances, fans & luminaries	✓			
Check any aftermarket items	✓			
Charge voltage	✓			

Testing Service Technician Name:

LPG Gas System (Technicians Handbook Section 4)
(Gas appliances not serviced unless requested)

	P	F	N/A	R
Regulator, gas hose, pipework & manifold	✓			
Carry out gas soundness check	✓			
Check security of LPG tank (if fitted)			✓	
Security of gas cylinder(s)	✓			
Ensure all gas dispersal vents are clear	✓			
Appliances – check operation of all gas appliances fitted including FFD's	✓			

Testing Service Technicians Name:

Water System (Technicians Handbook Section 5.6 & 5.7)

	P	F	N/A	R
Water pump & pressure switch/microswitches	✓			
Taps, valves, pipes & tank (if fitted)	✓			
Water inlets	✓			
Waste system	✓			
Toilet	✓			

Bodywork (Technicians Handbook Section 5)

	P	F	N/A	R
Doors & windows	✓			
General roof condition	✓			
Body attachments – check security (including ladders, cycle racks, lockers aerials, satellite dishes, etc)	✓			
Floor	✓			
Furniture	✓			
Blinds & fly screens	✓			
Damp test – carry out & note readings on a separate damp report sheet	✓			
Rising roof (if applicable)			✓	

Ventilation (Technicians Handbook Section 5.4)

	P	F	N/A	R
Fixed ventilation (low & high levels)	✓			
Roof lights	✓			

Fire & Safety (Technicians Handbook Section 5.5)

	P	F	N/A	R
Press test button on smoke alarm to test electrical circuitry & sound alarm (if fitted)	✓			
Press test button on CO alarm to test electrical circuitry & sound alarm (if fitted)	✓			
If a fire extinguisher is fitted, check security of its housing (see below)	✓			

Smoke and/or carbon monoxide alarm(s) if fitted:

Smoke alarm expiry date (if visible): **2025** Carbon monoxide alarm expiry date (if visible): **2027**

Fire extinguisher expiry date: **2022**

Important – All appliances are tested for operation only. This does not confirm that they are working to the prescribed standard. Additional servicing may be required for warranty purposes/products (e.g. fridge)

Part 1 of 2

9317 mls
101004254

Test drive

Test drive - 10 mins	
Further details	
Engine lights	
Further info	
Dashboard Ghosting / Mileage flashing	

Sign off

Completed by	
Date/Time	

CMS MOTORHOME INSPECTION FORM

In receiving this form you are automatically agreeing with this acknowledgment. Whilst it would be nice to have a full AA style report and professional habitation check, it is not realistic and we are not trained to do so, so take all descriptions & reports as the assessors opinion only. All of our listed checks were opinion of the assessor before the date of the auction, conditions of the motorhome or caravan are expected to change in that time. Take into consideration fair wear and tear for the age of the motorhome. We do not test heating, gas, electric, water systems or accessories. All motorhomes are driven to the auction unless stated. MOT history & mileage checks are public record for the buyer to do their basic due diligence with. This is a trade auction only and must be treated as such. Bidding is bound by British Car Auction terms and conditions. Please visit <https://www.bca.co.uk> for auction terms and conditions. Bid at your own risk.