

CMS MOTORHOME INSPECTION FORM



General

CMS Motorhome Inspection	
Make & Model	
Reg Number - NO GAP	
HPI Clear	
Engine Size	
BHP	
Transmission	
Miles or KM	
Mileage	
Confirm miles (within 5,000)	
Is Mileage Warranted	
How many sets of engine keys	

External Inspection

External Extras	
Any Other Extras	
Decals	
Further Info	
Decal Photos	
Any Damage Found	
Further Information	

CMS MOTORHOME INSPECTION FORM

<p>Damage Photos</p>	
	
<p>Windscreen</p>	
<p>Damage Photos</p>	
<p>Alloy Wheels</p>	
<p>Further Information</p>	
<p>Damage Photos</p>	
<p>Are the tyres illegal, cracking or out of date (6 years)</p>	

CMS MOTORHOME INSPECTION FORM

Further Info	
Tyre photos	
Electric Step	
Does self levelling work? (if applicable)	
Further comments	
Further Photo's	
Further info	

Engine Bay

Are fluid levels correct? oil/coolant/brake fluid	
More Info	
Engine bay check	
More info	


Internal layout

Berths	
Belts	
Lounge	
Bed options	
Layout correct	
Further Comments	
Multi Photo	
Further info	

Internal Inspection

Internal Extras	
Other extras	
Do the electrics turn on	
More info	
Control Panel Damaged? Screen/buttons	
More Info	
Does the stereo turn on	
Smell or signs of smoking	
Are all cushions correct including travel cushions	

CMS MOTORHOME INSPECTION FORM

Is the boiler present	
Are overhead lockers empty/objects secure ready for travel?	
Damage	
Damage info	
Damage photos	

Damp inspection

Damp (visible/Soft)	
Damp info	
Photos of any damp	
Floor damp/spongey/damaged	

CMS MOTORHOME INSPECTION FORM

Further info	
Floor photos	

Paperwork

V5 present	
Does the V5 vin match 2 x Vehicle vins	
Manuals present	
Engine Service History	
Engine Service info	
Engine Service photos	

Service sheets

Service intervals: **Vehicle mileage:** 9454

☒ Oil change + oil filter
☒ Air filter
☒ Cabin filter
☒ Fuel filter
☒ Brake fluid
☒ Coolant

☐ Spark plugs
☐ Timing belt
☐ Accessories belt
☐ Rear brake linings
☐ Air conditioning

Oil used (standard and grade):

Other operations:

Anti-corrosion check

Is the vehicle in good condition?
☒ yes ☐ no

Continuation of warranty subject to repair:

Date of repair: 05/05/09

Elite Motorhomes
 Thorpe Road
 Middleton Cheney
 Banbury, Oxon
 Tel: (01295) 711157

Next service due on: 05/05/10 or at: miles

Service intervals: **Vehicle mileage:** 17960

☒ Oil change + oil filter
☒ Air filter
☐ Cabin filter
☐ Fuel filter
☐ Brake fluid
☐ Coolant

☐ Spark plugs
☐ Timing belt
☐ Accessories belt
☐ Rear brake linings
☐ Air conditioning

Oil used (standard and grade):

Other operations:

Anti-corrosion check

Is the vehicle in good condition?
☒ yes ☐ no

Continuation of warranty subject to repair:

Date of repair: 19/12/2012

STOKE MANDEVILLE
AUTO CENTRE
 of
AYLESBURY
 01296 613002

Next service due on: or at: miles

CMS MOTORHOME INSPECTION FORM

Service sheets (cont.)

Service intervals:

☒ Oil change + oil filter
☐ Air filter
☐ Cabin filter
☐ Fuel filter
☐ Brake fluid
☒ Coolant

Oil used (standard and grade):

Other operations:

Vehicle mileage: 20530

☐ Spark plugs
☐ Timing belt
☐ Accessories belt
☐ Rear brake linings
☐ Air conditioning

Anti-corrosion check
 Is the vehicle in good condition?
☒ yes ☐ no

Continuation of warranty subject to repair:

Date of repair: 18/11/13

Elite Motorhomes
 Thorpe Road
 Middleton Cheney
 Banbury OX17 2QY
 Tel: (01295) 711157

Next service due on: or at: miles

Service intervals:

☒ Oil change + oil filter
☒ Air filter
☒ Cabin filter
☒ Fuel filter
☐ Brake fluid
☐ Coolant

Oil used (standard and grade):

Other operations:

Vehicle mileage: 23,900

☐ Spark plugs
☐ Timing belt
☐ Accessories belt
☐ Rear brake linings
☐ Air conditioning

Anti-corrosion check
 Is the vehicle in good condition?
☐ yes ☐ no

Continuation of warranty subject to repair:

Date of repair:

ACORN TYRES (AYLESBURY) LTD
 WESTON WAY INDUSTRIAL ESTATE
 LOWER ROAD, STOKE MANDEVILLE
 AYLESBURY, BUCKS HP22 5GT
 TEL: 01296 612075

Next service due on: or at: miles

CMS MOTORHOME INSPECTION FORM

(cont.)

Vehicle mileage: 27,454

ACORN TYRES (AYLESBURY) LTD
WESTON WAY INDUSTRIAL ESTATE
LOWER ROAD, STOKE MANDEVILLE
AYLESBURY, BUCKS HP22 5GT
TEL: 01296 612075

Service intervals: ☒ Oil change + oil filter ☐ Spark plugs
☒ Air filter ☐ Timing belt
☐ Cabin filter ☐ Accessories belt
☒ Fuel filter ☐ Rear brake linings
☐ Brake fluid ☐ Air conditioning
☐ Coolant

Oil used (standard and grade): _____

Other operations: _____

Anti-corrosion check
Is the vehicle in good condition?
☐ yes ☐ no

Continuation of warranty subject to repair: _____

Date of repair: _____

Stamp of RENAULT Dealer

Next service due on: _____ or at: _____ miles

Vehicle mileage: 33383

Service intervals: ☒ Oil change + oil filter ☐ Spark plugs
☒ Air filter ☐ Timing belt
☐ Cabin filter ☐ Accessories belt
☒ Fuel filter ☐ Rear brake linings
☐ Brake fluid ☐ Air conditioning
☐ Coolant

Oil used (standard and grade): _____

Other operations: _____

Anti-corrosion check
Is the vehicle in good condition?
☐ yes ☐ no

Continuation of warranty subject to repair: _____

Date of repair: _____

Stamp of RENAULT Dealer

Next service due on: _____ or at: _____ miles

23

CMS MOTORHOME INSPECTION FORM

Service sheets (cont.)

5/12/18 Vehicle mileage: 35 217

Service intervals:

- ☒ Oil change + oil filter
- ☒ Air filter
- ☒ Cabin filter
- ☒ Fuel filter
- ☐ Brake fluid
- ☐ Coolant

Oil used (standard and grade):

Other operations:

Anti-corrosion check

Is the vehicle in good condition?

☐ yes ☐ no

Continuation of warranty subject to repair:

Date of repair:

ACORN TYRES (AYLESBURY) LTD
WESTON WAY INDUSTRIAL ESTATE
LOWER ROAD, STOKE MANDEVILLE
AYLESBURY, BUCKS HP22 5GT
TEL: 01296 612075

Next service due on: or at: miles

30-05-2019 Vehicle mileage: 36 179

Service intervals:

- ☒ Oil change + oil filter
- ☒ Air filter
- ☐ Cabin filter
- ☒ Fuel filter
- ☐ Brake fluid
- ☐ Coolant

Oil used (standard and grade):

Other operations:

Anti-corrosion check

Is the vehicle in good condition?

☐ yes ☐ no

Continuation of warranty subject to repair:

Date of repair:

Elite Motorhomes
Thorne Road
Middleton Cheney
Banbury OX17 2QY
Tel: (01295) 711157

Next service due on: or at: miles

Habitation Service Reports	
Habitation service info	
Habitation service photos	

Test drive

Test drive - 10 mins	
Further details	
Engine lights	
Further info	
Dashboard Ghosting	

Sign off

CMS MOTORHOME INSPECTION FORM

Completed by	
Date/Time	
<p>In receiving this form you are automatically agreeing with this acknowledgment. Whilst it would be nice to have a full AA style report and professional habitation check, it is not realistic and we are not trained to do so, so take all descriptions & reports as the assessors opinion only. All of our listed checks were opinion of the assessor before the date of the auction, conditions of the motorhome or caravan are expected to change in that time. Take into consideration fair wear and tear for the age of the motorhome. We do not test heating, gas, electric, water systems or accessories. All motorhomes are driven to the auction unless stated. MOT history & mileage checks are public record for the buyer to do their basic due diligence with. This is a trade auction only and must be treated as such. Bidding is bound by British Car Auction terms and conditions. Please visit https://www.bca.co.uk for auction terms and conditions. Bid at your own risk.</p>	