

## CMS MOTORHOME INSPECTION FORM

### General

CMS Motorhome Inspection	
Make & Model	
Reg Number - NO GAP	
HPI Clear	
Engine Size	
BHP	
Transmission	
Miles or KM	
Mileage	
Confirm miles (within 5,000)	
Is Mileage Warranted	
How many sets of engine keys	
V5 present	
Does the V5 vin match 2 x Vehicle vins	


### Engine Bay

Are fluid levels correct? oil/coolant/brake fluid	
More Info	
Engine bay check	
More info	

### External Inspection

External Extras	
Any Other Extras	
Decals	
Further Info	
Decal Photos	
Any Damage Found	
Windscreen	
Damage Photos	
Alloy Wheels	
Further Information	

## CMS MOTORHOME INSPECTION FORM

<p>Damage Photos</p>	
<p>Are the tyres illegal, cracking or out of date (6 years)</p>	
<p>Further Info</p>	
<p>Tyre photos</p>	
<p>Electric Step</p>	
<p>Does self levelling work? (if applicable)</p>	
<p>Further comments</p>	
<p>Further Photo's</p>	
<p>Further info</p>	

## Internal layout

## CMS MOTORHOME INSPECTION FORM

Berths	
Belts	
Lounge	
Bed options	
Layout correct	
Further Comments	
Multi Photo	
Further info	

### Internal Inspection

Internal Extras	
Other extras	
Do the electrics turn on	
More info	
Control Panel Damaged? Screen/buttons	
More Info	
Does the stereo turn on	
Smell or signs of smoking	
Are all cushions correct including travel cushions	
Is the boiler present	
Are overhead lockers empty/objects secure ready for travel?	
Damage	
Damage info	

## CMS MOTORHOME INSPECTION FORM

Damage photos



### Damp inspection

Damp (visible/Soft)

## CMS MOTORHOME INSPECTION FORM

Damp info	
Photos of any damp	
Floor damp/spongey/damaged	
Further info	
Floor photos	

## Paperwork

Manuals present	
Engine Service History	
Engine Service info	

Engine Service photos

**Onecall Preston Limited**  
Riversdale Place  
The Industrial Estate  
Widnes  
Cheshire WA26 7QS  
Tel: 01772 433333

07511 908655  
**ONEcall**  
PRESTON LTD

\*\*\* Invoice \*\*\*

Invoice No: 146683  
Invoice Date: 19/08/2024  
Order No:  
Customer: ASH009

Page 1 of 2

Quantity	Rate	VAT	Net
0.50	75.00	7.50	37.50
Sub Total			37.50
1.00	55.00	0.00	55.00
Sub Total			55.00
1.00	150.00	30.00	150.00
Sub Total			150.00
6.20	16.95	21.02	105.09
1.00	25.50	5.10	25.50
1.00	60.70	12.14	60.70
1.00	29.70	5.94	29.70
1.00	4.00	0.80	4.00
Sub Total			224.99

**Labour**  
To Investigate Knocking Noise

**MOTs**  
MOT Test

**Gold Service**  
Gold Service

**Parts**  
OILS Fully Synthetic Engine oil  
Oil filter  
Fuel filter  
Pollen filter  
Environmental Charge

**Tyre Tread Depths (mm)**  
N/S/F: 5 O/S/F: 5 N/S/R1: 7 O/S/R1: 7 Spare 1:

**Technician Comments**  
No play in any suspension components, all tested ok.

Vehicle:	NX21 XKU
Make:	FIAT DUCATO 35 C/C MULTIJET II
VIN:	ZFA2500002R34493
Mileage:	13757
Technician:	GT/Ryan

Title to the goods supplied remain with this company until payment for them has been satisfactorily received - E & O E

Continued on the next page....

Invoice Totals	
Description	Amount
Vatable Items	412.49
VAT @ 20.00%	82.50
Zero Rated Items	55.00
<b>Total Invoice Value</b>	<b>549.99</b>

This cash invoice is due for payment



## CMS MOTORHOME INSPECTION FORM

**SCHEDULED SERVICING**

**N. MELLING & SONS LTD**  
**WESCOT GARAGE**

COUPON: 361 Croston Road  
ENGINE OIL: Farington Moss  
EXPECTED AT KM: Leyland  
PERFORMED AT KM: RR26 6PN  
Tel: 01772 432415  
VAT No: 45516541000  
6134

Motorhome Specialist  
Servicing  
20/9/23

MODEL: \_\_\_\_\_  
COUPON: \_\_\_\_\_  
ENGINE OIL CHANGE: \_\_\_\_\_  
EXPECTED AT KM: \_\_\_\_\_  
PERFORMED AT KM: \_\_\_\_\_  
CHASSIS NO.: \_\_\_\_\_  
STAMP AND SIGNATURE: \_\_\_\_\_  
DATE: \_\_\_\_\_

MODEL: \_\_\_\_\_  
COUPON: \_\_\_\_\_  
ENGINE OIL CHANGE: \_\_\_\_\_  
EXPECTED AT KM: \_\_\_\_\_  
PERFORMED AT KM: \_\_\_\_\_  
CHASSIS NO.: \_\_\_\_\_  
STAMP AND SIGNATURE: \_\_\_\_\_  
DATE: \_\_\_\_\_

MODEL: \_\_\_\_\_  
COUPON: \_\_\_\_\_  
ENGINE OIL CHANGE: \_\_\_\_\_  
EXPECTED AT KM: \_\_\_\_\_  
PERFORMED AT KM: \_\_\_\_\_  
CHASSIS NO.: \_\_\_\_\_  
STAMP AND SIGNATURE: \_\_\_\_\_  
DATE: \_\_\_\_\_

MODEL: \_\_\_\_\_  
COUPON: \_\_\_\_\_  
ENGINE OIL CHANGE: \_\_\_\_\_  
EXPECTED AT KM: \_\_\_\_\_  
PERFORMED AT KM: \_\_\_\_\_  
CHASSIS NO.: \_\_\_\_\_  
STAMP AND SIGNATURE: \_\_\_\_\_  
DATE: \_\_\_\_\_

MODEL: \_\_\_\_\_  
COUPON: \_\_\_\_\_  
ENGINE OIL CHANGE: \_\_\_\_\_  
EXPECTED AT KM: \_\_\_\_\_  
PERFORMED AT KM: \_\_\_\_\_  
CHASSIS NO.: \_\_\_\_\_  
STAMP AND SIGNATURE: \_\_\_\_\_  
DATE: \_\_\_\_\_

MODEL: \_\_\_\_\_  
COUPON: \_\_\_\_\_  
ENGINE OIL CHANGE: \_\_\_\_\_  
EXPECTED AT KM: \_\_\_\_\_  
PERFORMED AT KM: \_\_\_\_\_  
CHASSIS NO.: \_\_\_\_\_  
STAMP AND SIGNATURE: \_\_\_\_\_  
DATE: \_\_\_\_\_

Has the cam belt been changed? (5 years on all ford 2.0 and fiat 2.3)	
Cam belt change info	
Cam belt change invoice	
Habitation Service Reports	
Habitation service info	
Habitation service photos	

### Test drive

Test drive - 10 mins	
Further details	

## CMS MOTORHOME INSPECTION FORM

Engine lights	
Further info	
Dashboard Ghosting	

### Sign off

Completed by	
Date/Time	
<p>In receiving this form you are automatically agreeing with this acknowledgment. Whilst it would be nice to have a full AA style report and professional habitation check, it is not realistic and we are not trained to do so, so take all descriptions &amp; reports as the assessors opinion only. All of our listed checks were opinion of the assessor before the date of the auction, conditions of the motorhome or caravan are expected to change in that time. Take into consideration fair wear and tear for the age of the motorhome. We do not test heating, gas, electric, water systems or accessories. All motorhomes are driven to the auction unless stated. MOT history &amp; mileage checks are public record for the buyer to do their basic due diligence with. This is a trade auction only and must be treated as such. Bidding is bound by British Car Auction terms and conditions. Please visit <a href="https://www.bca.co.uk">https://www.bca.co.uk</a> for auction terms and conditions. Bid at your own risk.</p>	