


## CMS MOTORHOME INSPECTION FORM


### General

CMS Motorhome Inspection	
Make & Model	
Reg Number (in capitals - no gap)	
HPI Clear	
Engine Size	
BHP	
Transmission	
Miles or KM	
Mileage	
Confirm miles (within 5,000)	
Is Mileage Warranted	
How many sets of engine keys	

### External Inspection

External Extras	
Any Other Extras	
Decals	
Further Info	
Decal Photos	
Any Damage Found	

## CMS MOTORHOME INSPECTION FORM

Further Information	
Damage Photos	
Windscreen	
Alloy Wheels	
Electric Step	
Does self levelling work? (if applicable)	
Further comments	
Further Photo's	
Further info	

### Engine Bay

Are fluid levels correct? oil/coolant/brake fluid	
More Info	
Engine bay check	
More info	

### Internal layout

Berths	
Belts	
Lounge	
Bed options	
Layout correct	

## CMS MOTORHOME INSPECTION FORM

Further Comments	
Multi Photo	
Further info	

### Internal Inspection


Internal Extras	
Other extras	
Do the electrics turn on	
More info	
Control Panel Damaged? Screen/buttons	
More Info	
Does the stereo turn on	
Smell or signs of smoking	
Are all cushions correct including travel cushions	
Is the boiler present	
Are overhead lockers empty/objects secure ready for travel?	
Damage	
Damage info	

## CMS MOTORHOME INSPECTION FORM

Damage photos



## CMS MOTORHOME INSPECTION FORM



## CMS MOTORHOME INSPECTION FORM



## CMS MOTORHOME INSPECTION FORM



### Damp inspection

Damp (visible/Soft)	
Damp info	
Photos of any damp	
Floor damp/spongey/damaged	
Further info	
Floor photos	

### Paperwork

V5 present	
Does the V5 vin match 2 x Vehicle vins	
Manuals present	
Engine service history	
Engine Service Info	





## CMS MOTORHOME INSPECTION FORM

Engine Service photos

09:33
4G

Document.pdf


**Hartwell Dunstable**  
77-87 London Road, Dunstable,  
Bedfordshire, LU6 3DT  
Tel: 01582 443500  
Email: f65sm@hartwell.co.uk  
Hartwell Automotive Group Limited  
Reg'd in England no 0158447 VAT No: 194 3655 35  
The registered office for the companies shown above is:  
Wootton Business Park, Besselsleigh Road,  
Wootton, Oxon, OX13 6FD


<b>Invoice To Name &amp; Address</b> Toni Wise	<b>Driver Name &amp; Address</b> Toni Wise	<b>Invoice Number:</b> S 226295 <b>Invoice Date:</b> 03/09/2024 <b>Order No:</b> <b>Customer Ref:</b> W0000361 <b>Status:</b> Cash <b>Cust. Advisor:</b> E Martin <b>Franchise:</b> <b>Workshop:</b> <b>Invoice By:</b> mabasi <b>Jobsheet No:</b> 347929
---	---	--

**Vehicle Details**

<b>Reg:</b> PE21 UHH	<b>Chassis No:</b> WF00XTTROL885588	<b>Mileage in:</b> 31392	<b>Out:</b> 31392 miles
<b>Vehicle:</b> Ford Transit	<b>Engine No:</b> NOT KNOWN		

**Repair A**

**Work Carried Out**

<b>Description</b> Job Sheet No. 347929 VRL - Free visual health check	<b>Total Nett</b> £0.00
--	----------------------------

Repair Totals	Total Labour	Total Parts	Repair Total
	£0.00	£0.00	£0.00

**Repair B**

**Work Carried Out**

Replace Engine Oil & Oil Filter - £265.50	
<b>Description</b> Replace Engine Oil & Oil Filter - £265.50	<b>Total Nett</b> £131.69



**Parts & Materials**

Part Number	Description	RRP	Unit Price	Qty	Total Nett
2007929	FILTER ASSY - OIL	£17.96	£17.96	1.00	£17.96
0W30	0W30 CASTROL MAG PROF	£11.05	£7.00	9.80	£68.60
<b>Repair Totals</b>		<b>Total Labour</b>	<b>Total Parts</b>	<b>Repair Total</b>	
		£131.69	£36.56	£218.25	

**Payments Made**





Card Payment	£261.90
--------------	---------

Page 1 of 2
Invoice Number: S 226295





**Hartwell Dunstable**  
77-87 London Road, Dunstable,  
Bedfordshire, LU6 3DT  
Tel: 01582 443500  
Email: f65sm@hartwell.co.uk  
Hartwell Automotive Group Limited  
Reg'd in England no 0158447 VAT No: 194 3655 35  
The registered office for the companies shown above is:  
Wootton Business Park, Besselsleigh Road,  
Wootton, Oxon, OX13 6FD




## CMS MOTORHOME INSPECTION FORM

Habitation Service Reports																				
Habitation service info																				
Habitation service photos	<div> <div> <b>MOTORHOME ANNUAL HABITATION INSPECTION</b> </div> <div>  <p><b>Marquis Service</b></p> <p>The UK's Largest Dealer Network</p> </div> </div> <table border="1"> <tr> <td>Customer: Mrs Wise</td> <td>Date: 21/03/24</td> <td>Job No. 50953</td> </tr> <tr> <td>Make: Benimar</td> <td>Model: Tessoro T483</td> <td>Reg No or VIN: PE21 UAH</td> </tr> <tr> <td>Serial No: -</td> <td>Mileage: 2259</td> <td>Next Habitation Inspection:</td> </tr> </table> <p>Marquis carry out Habitation Inspections and Repairs to both Touring Caravans and Motorhomes.</p> <p>All work is carried out in accordance with the current Approved Workshop Scheme Standards.</p> <p>The following list is the breakdown of the areas that will be checked during the Habitation Inspection:</p> <table> <tr> <td><input checked="" type="checkbox"/> Gas</td> <td><input checked="" type="checkbox"/> Appliances</td> </tr> <tr> <td><input checked="" type="checkbox"/> 12v Electrics</td> <td><input checked="" type="checkbox"/> Ventilation</td> </tr> <tr> <td><input checked="" type="checkbox"/> 230v Mains Electrics</td> <td><input checked="" type="checkbox"/> Fire Safety</td> </tr> <tr> <td><input checked="" type="checkbox"/> Water System</td> <td><input checked="" type="checkbox"/> Bodywork</td> </tr> <tr> <td><input checked="" type="checkbox"/> Damp Survey</td> <td></td> </tr> </table> <div>  <p><b>APPROVED WORKSHOP</b></p> <p><b>ncc</b></p> </div> <div> <p><b>IMPORTANT NOTICE</b></p> <p>The Habitation Inspection does not include servicing of the base vehicle and road legal requirements. Appliances are checked for operation only, additional servicing may be required for warranty purposes.</p> </div> <div>  <p><b>3 YEARS UNLIMITED MILEAGE GUARANTEE</b></p> <p><b>AutoMarq</b> QUALITY USED MOTORHOMES</p> <p>INCLUDED WITH ALL USED MOTORHOMES</p> </div> <div>  </div> <p><b>www.marquisleisure.co.uk</b></p> <p><small>Auto-Sleepers Group Limited, Registered Office, Orchard Works, Willersley, Nr Broadway, Worcestershire, WR12 7QP. Reg. No: 3978237 VAT No: 747 888 363 (Marquis South Yorkshire Limited Reg. No: 3302024 VAT No: 179 679 432)</small></p>	Customer: Mrs Wise	Date: 21/03/24	Job No. 50953	Make: Benimar	Model: Tessoro T483	Reg No or VIN: PE21 UAH	Serial No: -	Mileage: 2259	Next Habitation Inspection:	<input checked="" type="checkbox"/> Gas	<input checked="" type="checkbox"/> Appliances	<input checked="" type="checkbox"/> 12v Electrics	<input checked="" type="checkbox"/> Ventilation	<input checked="" type="checkbox"/> 230v Mains Electrics	<input checked="" type="checkbox"/> Fire Safety	<input checked="" type="checkbox"/> Water System	<input checked="" type="checkbox"/> Bodywork	<input checked="" type="checkbox"/> Damp Survey	
Customer: Mrs Wise	Date: 21/03/24	Job No. 50953																		
Make: Benimar	Model: Tessoro T483	Reg No or VIN: PE21 UAH																		
Serial No: -	Mileage: 2259	Next Habitation Inspection:																		
<input checked="" type="checkbox"/> Gas	<input checked="" type="checkbox"/> Appliances																			
<input checked="" type="checkbox"/> 12v Electrics	<input checked="" type="checkbox"/> Ventilation																			
<input checked="" type="checkbox"/> 230v Mains Electrics	<input checked="" type="checkbox"/> Fire Safety																			
<input checked="" type="checkbox"/> Water System	<input checked="" type="checkbox"/> Bodywork																			
<input checked="" type="checkbox"/> Damp Survey																				

## CMS MOTORHOME INSPECTION FORM

DAMP SURVEY		
<div style="border: 1px solid black; padding: 5px; text-align: center;"> <b>Front</b>  0%  <b>Rear</b> </div> <p style="text-align: center;">Roof</p>	<div style="border: 1px solid black; padding: 5px; text-align: center;"> <b>Front</b>  0%  <b>Rear</b> </div> <p style="text-align: center;">External Floor</p>	<div style="border: 1px solid black; padding: 5px; text-align: center;"> <b>Front</b> 8 8 8 8 <b>Rear</b> </div> <p style="text-align: center;">Internal Floor</p>
		
		
		
<p><b>Results:</b></p> <ul style="list-style-type: none"> <li>Readings between (0-15%) - no cause for concern.</li> <li>Readings between (16-20%) - may require further investigation. Recommend recheck the affected area in 3 months.</li> <li>Readings between (21-30%) - moisture evident possible remedial work required; may not need stripdown unless surface damage (staining, pimpling, softness) is apparent. (There may be a risk of wallboard deterioration due to retained moisture in structure if resealed only.)</li> <li>Readings (31% and above) - Possible structural damage may be occurring. Full stripdown of the affected area is recommended to ascertain level of repair required.</li> </ul>		
<p style="text-align: right;">Damp Meter Accuracy Reading <span style="border: 1px solid black; display: inline-block; width: 50px; height: 15px;"></span></p>		

### Test drive

Test drive	
Further details	
Engine lights	
Further info	
Dashboard Ghosting	

### Sign off

Completed by	
Date/Time	

## CMS MOTORHOME INSPECTION FORM

In receiving this form you are automatically agreeing with this acknowledgment. Whilst it would be nice to have a full AA style report and professional habitation check, it is not realistic and we are not trained to do so, so take all descriptions & reports as the assessors opinion only. All of our listed checks were opinion of the assessor before the date of the auction, conditions of the motorhome or caravan are expected to change in that time. Take into consideration fair wear and tear for the age of the motorhome. We do not test heating, gas, electric, water systems or accessories. All motorhomes are driven to the auction unless stated. MOT history & mileage checks are public record for the buyer to do their basic due diligence with. This is a trade auction only and must be treated as such. Bidding is bound by British Car Auction terms and conditions. Please visit <https://www.bca.co.uk> for auction terms and conditions. Bid at your own risk.