

## CMS MOTORHOME INSPECTION FORM

### General Information

Make & Model	Bailey Autograph 79-4T
Reg Number - NO GAP	PO18CEX
HPI Clear	Yes
VAT	No
Engine Size	2.0
BHP	160
Transmission	Manual
Miles or KM	Miles
Mileage	12792
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	
V5 present	Yes

### Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

## CMS MOTORHOME INSPECTION FORM

### Mechanical Inspection

Brake Pedal Pressure Pass?	Yes
Handbrake Test Pass?	Yes
Static Gear Selection Pass?	Yes
Clutch Slip Test Pass?	Yes
Steering Noise	No
Engine noise	No

### Test Drive

Test drive - 10 mins	Pass
Engine Lights	No
Engine Lights Info	
Dashboard Ghosting	Yes
Cruise Control Comment	

## CMS MOTORHOME INSPECTION FORM

### External Inspection

External Extras	Alloys, Awning, BBQ point, Reversing camera, Tow bar, Solar panel, Tv Aerial
Decals	Need attention
Decals Further Info	Passenger door bubbling // slight peeling os //
Any Damage Found	Yes
Damage Further Info	Slight scratch ns bumper // slight scratches os rear bumper // large scratch os window //
Windscreen	No damage
Alloy Wheels	Need attention
Alloy Wheels Further Info	Slight oxidation ns rear // slight oxidation os rear //
Tyres Illegal/Cracking/Out of Date	No
Tyre Further Info	
Damp Floor Underneath	No
Damp Further Info	
Electric Step	N/A
Self Levelling Work	N/A
Pop Top Canvas Damage	N/A

## CMS MOTORHOME INSPECTION FORM

### Internal Inspection

Internal Look Original	
Berths	4
Belts	4
Bed Options	Bench Seats, Single Beds
Lounge Layout	Half Dinette
Layout Correct	Yes
Further Comments	No
Further Comments Info	
Internal Extras	DAB radio, cab A/C, Cruise control, Multifunction steering wheel, Part leather, Bluetooth, Hill descent control, Tv(s), Oven
Other Extras	
Electrics Turn On	Yes
Control Panel Damaged	No
Stereo Turn On	Yes
Smell or Signs of Smoking	No
Cushions Correct	Yes
Boiler Present	Yes
Overhead Lockers Ready	Yes

## CMS MOTORHOME INSPECTION FORM

### Internal Damage & Damp Check

Internal Damage	Yes
Damage Info	Dink on bedside table // hole in garage door //
Damp Visible/Soft	No
Floor Damp/Spongy/Damaged	No
Manuals Present	Yes

### Service History

Engine Service History	Partial
Service Info	
Cam Belt Changed	No
Habitation Service Reports	Partial
Habitation Info	
V5 Tested on DVLA	Yes
All Stages Completed	Yes
Completed By	Keenan Parnell
Sign-off Date	
Price Guide	

## CMS MOTORHOMES INSPECTION FORM - PHOTOS

### V5 Document Photos




Photo 1




Photo 2



Photo 3

## CMS MOTORHOME INSPECTION FORM - PHOTOS

## Vehicle VIN Photos



Photo 1



Photo 2

## CMS MOTORHOME INSPECTION FORM - PHOTOS

### External Damage Photos



Photo 1



Photo 2



Photo 3



## CMS MOTORHOME INSPECTION FORM - PHOTOS

### Decal Photos



Photo 1



Photo 2

## CMS MOTORHOME INSPECTION FORM - PHOTOS

### Alloy Damage Photos



Photo 1



Photo 2

## CMS MOTORHOME INSPECTION FORM - PHOTOS

### Internal Damage Photos




Photo 1



Photo 2