

## General


CMS Motorhome Inspection	
Make & Model	
Reg Number (in capitals - no gap)	
HPI Clear	
Engine Size	
BHP	
Transmission	
Miles or KM	
Mileage	
Confirm miles (within 5,000)	
Is Mileage Warranted	
How many sets of engine keys	

#### **External Inspection**

External Extras	
Any Other Extras	
Decals	
Further Info	





**Decal Photos** 






Damage Photos



















































Are fluid levels correct? oil/coolant/brake fluid




More Info	
Engine bay check	
More info	
Internal layout	
Berths	
Belts	
Lounge	
Bed options	
Layout correct	
Further Comments	
Multi Photo	
Further info	
Internal Inspection	
Internal Extras	
Other extras	
Do the electrics turn on	
More info	
Control Panel Damaged? Screen/buttons	
More Info	
Does the stereo turn on	
Smell or signs of smoking	
Are all cushions correct including travel cushions	
Is the boiler present	
Are overhead lockers empty/objects secure ready for travel?	
Damage	
Damage info	



Damage photos





#### **Damp inspection**


Damp (visible/Soft)	
Damp info	




Photos of any damp



































Floor photos








#### Paperwork

V5 present	
Does the V5 vin match 2 x Vehicle vins	
Manuals present	
Engine service history	
Engine Service info	







	Plant & CC www.geofficibey.co.uk	CARDANNE NAVIS BASES CARDANNE NAVIS BASES CARDANNE NAVIS BASES CARDANNE NAVIS BASES CARDANNE NAVIS BASES CARDANNE NAVIS BASES CARDANNE NAVIS BASES CARDANNE NAVIS BASES CARDANNE NAVIS BASES CARDANNE NAVIS BASES CARDANNE NAVIS BASES CARDANNE NAVIS CARDANNE CARDANNE NAVIS CARDANNE CARDAN	And a set of the set o	の一日の
Vehicle Issuers and Work Description	Registration: POSAEX Find Ducate 2006 2.8 dilowed - WHITE Wark Description Desmanting: AS INCOSEARY TO REMOVE AND REPU CARRY OUT IF SERVICE REPLACE STORTING RULDS	NCE CAMELLY, GUIDE AND TONSIONER	Minage CEIN We ZIKAHOODETHETH	
Work performed	ALUS MOT TIST 4.00 MOT Labour CLOSE 4 MOT TIST - (NOT) Labour Labour A SERVICE CAMERIT LABOUR	No. Date Price 100 4100 No. 4100 100 510 100 510 100 510	0.0 46.0 NCT Subtrail 146.8 Val 5 Ket Total 4 20.0 50.0 20.0 220.00	
	Parts Parts Canetta Contestination Contestination Parts Advances Possauca Motical RUSPH WASTE Co. 4: FRITR OBJOCAL Study HANDR Study School RC Co. Ex-2004 HANDR Ex-2004 HANDR	Part No. Cry. East Mo.   BFGMR2 1.00 10.01   GUT62030405 1.00 10.02   BG125 1.00 10.02   BVV 1.00 64   SUMP 1.00 578 64   H0380 2.00 1.11 1.11	2 200 18.22 200 18.09 5 200 18.65 5 200 4.65 2 20 8.68 2 20 2.22 Parts SchTatt 123727 1.0hort 155.00	
Invoice Total	VAT Celefe Rate % Net Total VAT Total (#) 0.00 46.00 0.00 (1) 210.00 489.72 97.54	987 No. 963453834	Parts 20172 VAT 97.94 Invoice Total 6633.66 Page 1 of 2	L
-2.1669 D	Compary New Yorkins, P 21 Church Road, Parketone, P	sole, Doniel, Brija Bur	C. C	



	the second state of the se		
	GEOF Plant & Co www.geoffkilbey.ca.uk	info@geoffkilbey.co.uk 01.425 6203	
all the	No. VENDO	Geoff Kilbey (Plant & Commercial) Ltd Callo Avenue New Mercon HANYS BH25 SQA	Invoice 5092212 Due 69-04-2024 (955 AM Job 205953
Vehicle Insurs and Work	Registration: PO56JZA Flat Ducate 2006 2.8 Diesel - WHITE		Mileage: 50872 VNc: 21A24400007700778
Description	Work Description CARRY OUT CLASS 4 MOIT TEST	a management of	- Second
Work performed	MOT Labour	Hes Unit Price	VAT % Net Total
	CLASS 4 MOT TEST - (MOT)	1.00 46.00	0.0 46.00 MOT SubTotal 246.00
Invoice Total	VAT Code Rate % Net Total VAT Total   (4) 0.00 46.00 0.00		Labour 46.00 Parts 0.00
de la companya de la	ALL ALL ALL	Invo	ice Total £46.00
and the second se	For BACS payments please note our Bank Details: Nati	Nest, Sort Code: 51-81-43, A/c: 88130230	
and the second se	Title to the goods supplied remain with this company i	until payment for them has been satisfactorily received - E & O	C C
and the second se			
and the second se			1000
			100 C
			a start and a start
and the second se			
	Company No. 06767991 21 Church Road, Parkstone, Poole	VAT No. 983455874 Docset, BH34 8UF	Page 1 of 1
and the second	State of the second	and a state of the state of the	
Habitation Service Reports			
Habitation service info			
Habitation service photos			
Test drive			
Test drive			
Further details			
Engine lights			
Further info			
Dashboard Ghosting			



# Sign off

Completed by	
Date/Time	
In receiving this form you are automatically agreeing with this acknowledgment. Whilst it would be nice to have a full AA style report and professional habitation check, it is not realistic and we are not trained to do so, so take all descriptions & reports as the assessors opinion only. All of our listed checks were opinion of the auction, conditions of the motorhome or caravan are expected to change in that time. Take into consideration fair wear and tear for the age of the motorhome. We do not test heating, gas, electric, water systems or accessories. All motorhomes are driven to the auction unless stated. MOT history & mileage checks are public record for the buyer to do their basic due diligence with. This is a trade auction only and must be treated as such. Bidding is bound by British Car Auction terms and conditions. Please visit https://www.bca.co.uk for auction terms and conditions. Bid at your own risk.	e t