

## CMS MOTORHOME INSPECTION FORM

### General Information

Make & Model	LANDSEER FORD CUSTOM
Reg Number - NO GAP	PO70GWC
HPI Clear	Yes
VAT	No
Engine Size	2.0
BHP	128
Transmission	Manual
Miles or KM	Miles
Mileage	16426
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	
V5 present	Yes

### Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

## CMS MOTORHOME INSPECTION FORM

### Mechanical Inspection

Brake Pedal Pressure Pass?	Yes
Handbrake Test Pass?	Yes
Static Gear Selection Pass?	Yes
Clutch Slip Test Pass?	Yes
Steering Noise	No
Engine noise	No

### Test Drive

Test drive - 10 mins	Pass
Engine Lights	No
Engine Lights Info	
Dashboard Ghosting	No
Cruise Control Comment	

## CMS MOTORHOME INSPECTION FORM

### External Inspection

External Extras	Alloys, Awning, Bike Rack, Electric step, LED daytime running lights, Parking sensors, Solar panel
Decals	N/A
Decals Further Info	
Any Damage Found	Yes
Damage Further Info	4 small dings on rear offside panel below window
Windscreen	No damage
Alloy Wheels	Good
Alloy Wheels Further Info	
Tyres Illegal/Cracking/Out of Date	No
Tyre Further Info	
Damp Floor Underneath	No
Damp Further Info	
Electric Step	Fully Working
Self Levelling Work	N/A
Pop Top Canvas Damage	No

## CMS MOTORHOME INSPECTION FORM

### Internal Inspection

Internal Look Original	Yes
Berths	4
Belts	5
Bed Options	Campervan
Lounge Layout	Bench Seats
Layout Correct	Yes
Further Comments	No
Further Comments Info	
Internal Extras	Auto headlights, Bluetooth, cab A/C, Cruise control, DAB radio, Diesel heater, Leather, Multifunction steering wheel, Oven
Other Extras	Electric blinds in rear
Electrics Turn On	No
More Info	Vehicle electrics work fine. No power to hab electrics
Control Panel Damaged	No
Stereo Turn On	Yes
Smell or Signs of Smoking	No
Cushions Correct	Yes
Boiler Present	N/A
Overhead Lockers Ready	Yes

## CMS MOTORHOME INSPECTION FORM

### Internal Damage & Damp Check

Internal Damage	Yes
Damage Info	Electric blind on sliding habitation door door not working
Damp Visible/Soft	No
Floor Damp/Spongy/Damaged	No
Manuals Present	Yes

### Service History

Engine Service History	Full
Service Info	
Cam Belt Changed	No
Habitation Service Reports	None
V5 Tested on DVLA	Yes
All Stages Completed	Yes
Completed By	Tim Craner
Sign-off Date	
Price Guide	

## CMS MOTORHOME INSPECTION FORM - PHOTOS

### V5 Document Photos



Photo 1



Photo 2




Photo 3

CMS MOTORHOME INSPECTION FORM - PHOTOS

Vehicle VIN Photos



Photo 1



Photo 2

## CMS MOTORHOME INSPECTION FORM - PHOTOS

### External Damage Photos



Photo 1