

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Rapido 924F
Reg Number - NO GAP	RX04RNV
HPI Clear	Yes
VAT	Yes
Engine Size	2.8
BHP	125
Transmission	Manual
Miles or KM	Miles
Mileage	65557
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	
V5 present	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass?	Yes
Handbrake Test Pass?	Yes
Static Gear Selection Pass?	Yes
Clutch Slip Test Pass?	Yes
Steering Noise	No
Engine noise	Yes
More Info	Squeaky noise //

Test Drive

Test drive - 10 mins	Pass
Engine Lights	No
Engine Lights Info	
Dashboard Ghosting	No
Cruise Control Comment	

CMS MOTORHOME INSPECTION FORM

External Inspection

External Extras	Awning, Tow bar, Reversing camera, Bike Rack, Ladder, Solar panel, Tv Aerial, Satellite dome, Electric step
Decals	Need attention
Decals Further Info	Peeling front bonnet // Rear streaky // ns faded // os faded //
Any Damage Found	Yes
Damage Further Info	Both wings paint flake // silicon peeling ns front // ns bad repair job // bonnet paint peeling // os front silicone peeling // os and ns rear both scratches // os locker door doesn't open //
Windscreen	Chip(s) smaller than 10p
Alloy Wheels	N/A
Alloy Wheels Further Info	
Tyres Illegal/Cracking/Out of Date	Yes
Tyre Further Info	Ns rear cracked //
Damp Floor Underneath	Yes
Damp Further Info	Dry rot os //
Electric Step	Fully Working
Self Levelling Work	N/A
Pop Top Canvas Damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Look Original	Yes
Berths	4
Belts	4
Bed Options	Bench Seats, Overcab Bed
Lounge Layout	Half Dinette
Layout Correct	Yes
Further Comments	No
Further Comments Info	
Internal Extras	Cruise control, Cab blinds, Habitation A/C, Tv(s)
Other Extras	
Electrics Turn On	Yes
Control Panel Damaged	No
Stereo Turn On	Yes
Smell or Signs of Smoking	No
Cushions Correct	Yes
Boiler Present	Yes
Overhead Lockers Ready	Yes

CMS MOTORHOME INSPECTION FORM

Internal Damage & Damp Check

Internal Damage	Yes
Damage Info	Ns window wallpaper peeling //
Damp Visible/Soft	Yes
Damp Info	Ns above cab blue staining // os above cab blue staining // inside rear locker blue staining // ceiling skylight blue staining //
Floor Damp/Spongy/Damaged	Yes
Floor Info	Floor near hab door all soft //
Manuals Present	Yes

Service History

Engine Service History	Partial
Service Info	
Cam Belt Changed	Yes
Cam Belt Info	9/3/21
Habitation Service Reports	None
V5 Tested on DVLA	Yes
All Stages Completed	Yes
Completed By	Keenan Parnell
Sign-off Date	
Price Guide	

CMS MOTORHOME INSPECTION FORM - PHOTOS

V5 Document Photos




Photo 1




Photo 2




Photo 3

CMS MOTORHOME INSPECTION FORM - PHOTOS

Vehicle VIN Photos




Photo 1




Photo 2

CMS MOTORHOME INSPECTION FORM - PHOTOS

External Damage Photos




Photo 1




Photo 2




Photo 3




Photo 4




Photo 5




Photo 6




Photo 7

CMS MOTORHOME INSPECTION FORM - PHOTOS

Decal Photos




Photo 1




Photo 2




Photo 3




Photo 4

CMS MOTORHOME INSPECTION FORM - PHOTOS

Windscreen Damage Photos




Photo 1

CMS MOTORHOME INSPECTION FORM - PHOTOS

Tyre Photos




Photo 1

CMS MOTORHOME INSPECTION FORM - PHOTOS

Internal Damage Photos




Photo 1

CMS MOTORHOME INSPECTION FORM - PHOTOS

Floor Photos




Photo 1

CMS MOTORHOME INSPECTION FORM - PHOTOS

Cam Belt Invoice Photo



Photo 1

CMS MOTORHOME INSPECTION FORM - PHOTOS

Damp Photos




Photo 1




Photo 2




Photo 3




Photo 4