

CMS MOTORHOME INSPECTION FORM

General

CMS Motorhome Inspection	
Make & Model	
Reg Number - NO GAP	
HPI Clear	
VAT	
Engine Size	
BHP	
Transmission	
Miles or KM	
Mileage	
Confirm miles (within 5,000)	
Is Mileage Warranted	
How many sets of engine keys	
V5 present	
Does the V5 vin match 2 x Vehicle vins	

Engine Bay

Are fluid levels correct? oil/coolant/brake fluid	
More Info	
Oil/Coolant Contamination	
More Info	
Engine bay check	
More info	

Mechanical Inspection

Brake Pedal Pressure Pass?	
More Info	
Handbrake Test Pass?	
More info	
Static Gear Selection (engine running) Pass?	
More info	
Clutch Slip Test Pass?	

CMS MOTORHOME INSPECTION FORM

More Info	
Steering Noise	
More Info	
Engine noise	
More info	
Video of engine running	

External Inspection


External Extras	
Any Other Extras	
Decals	
Further Info	

CMS MOTORHOME INSPECTION FORM

Decal Photos




CMS MOTORHOME INSPECTION FORM

	
Any Damage Found	
Further Information	

CMS MOTORHOME INSPECTION FORM


Damage Photos




CMS MOTORHOME INSPECTION FORM




CMS MOTORHOME INSPECTION FORM




CMS MOTORHOME INSPECTION FORM




CMS MOTORHOME INSPECTION FORM




CMS MOTORHOME INSPECTION FORM



CMS MOTORHOME INSPECTION FORM

	
Windscreen	

CMS MOTORHOME INSPECTION FORM

<p>Damage Photos</p>	
	
Alloy Wheels	
Further Information	
Damage Photos	
Are the tyres illegal, cracking or out of date (6 years)	
Further Info	
Tyre photos	
Electric Step	

CMS MOTORHOME INSPECTION FORM

Does self levelling work? (if applicable)	
Any damage to the pop top canvas?	
Pop top photos	
Further comments	
Further Photo's	
Further info	

Internal layout

Berths	
Belts	
Lounge	
Bed options	
Layout correct	
Further Comments	
Multi Photo	
Further info	

Internal Inspection

Internal Extras	
Other extras	
Do the electrics turn on	
More info	
Control Panel Damaged? Screen/buttons	
More Info	
Does the stereo turn on	
Smell or signs of smoking	
Are all cushions correct including travel cushions	
Is the boiler present	
Are overhead lockers empty/objects secure ready for travel?	
Damage	
Damage info	

CMS MOTORHOME INSPECTION FORM

Damage photos



Damp inspection


Damp (visible/Soft)	
Damp info	

CMS MOTORHOME INSPECTION FORM

Photos of any damp



CMS MOTORHOME INSPECTION FORM

	
Floor damp/spongey/damaged	
Further info	
Floor photos	

Paperwork

Manuals present	
Engine Service History	
Engine Service info	

CMS MOTORHOME INSPECTION FORM

Engine Service photos

Handy Group Ltd
School Lane
Chandlers Ford Industrial Estate
Eastleigh
Hampshire
SO53 4DG
www.handy.co.uk
Tel: 02380 483106
Fax: 02380 579229

SALE
AMOUNT £1,425.36
TOTAL £1,425.36

PIN VERIFIED
PLEASE RETAIN FOR YOUR RECORDS
Thank You

04/04/25 09:23
AUTH CODE: K94107

CUSTOMER COPY
PLEASE RETAIN RECEIPT

Make & Model: Ford Chausson Titanium 540 Aut
Chassis No.: YNF6
Engine No.: 14603
Mileage In: 13218
Mileage Out: 13218
Reg No.: DB06GET
Reg Date: 14/05/2019
Vehicle No.: 1723170
Carriage: 14603
W.P. No.: 120179
Job No.:
Next Service Date: 14/05/2025
Next MOT Date: 13/05/2025

Description of Goods / Services	Qty	Unit Price	Unit	Net Total	V
A LAB	5.20	135.00		702.00	S
CAMBELT CHANGE AND OIL SUMP					
X F2631801 V-BELT	1.00	86.35	86.35 EACH	15.00	73.40 S
X F2344230 BOLT	1.00	2.08	2.08 EACH	10.00	1.86 S
X F2715824 COVER - TIMING BELT	1.00	146.83	146.83 EACH	15.00	134.81 S
X F2361304 V-BELT	1.00	33.70	33.70 EACH	10.00	20.33 S
X F2018353 V-BELT	1.00	15.58	15.58 EACH	10.00	14.03 S
X F2018353 V-BELT	1.00	5.70	5.70 EACH	10.00	5.13 S
X F2011524 BOLT - HEX HEAD	1.00	35.31	35.31 EACH	10.00	31.78 S
X F2608131 PAN ASSY - ENGINE OI	1.00	17.96	17.96 EACH	10.00	16.17 S
X F2007829 FILTER ASSY - OIL	1.00	32.40	32.40 EACH	10.00	29.16 S
X F2011555 DRIVE BELT - OIL PUM	1.00	11.67	11.67 EACH	10.00	10.61 S
X F2283198 TUBE ASSY - OIL PUMP	2.00	20.23	20.23 EACH	10.00	36.42 S
X F2633427 SEALANT - SILICONE	110.00	1.20	1.20 EACH	15.00	112.20 S
X OCAS030 FORD 0W30 ENGINE OIL					
Menu Subtotal:				1187.80	

	V	Rate	Service/Goods	VAT	Net	1187.80
Parts	S	20.00	1187.80	237.56	Net	1187.80
Surcharge					V.A.T.	237.56
Labour					Total	1425.36
Sublet					Paid	1425.36
Menus					Owing	0.00

Bank Details: HSBC UK Bank PLC
Account Name: Handy Group Limited
Account Number: 40-42-18, 03856186

Reg Office: School Lane, Chandlers Ford, Hampshire SO53 4DG
Registered in England No: 192672 VAT No: GB 568 7215 08

Has the cam belt been changed?
(5 years on all ford 2.0 and fiat
2.3)

Cam belt change info

CMS MOTORHOME INSPECTION FORM

Cam belt change invoice

SCHOOL LANE WSH
EASTLEIGH
M11 00031
TID: 000140
SCH ID: MCE772740404
HANDSET: 1
MASTERCARD
AID: A0000000041010
Mastercard
*****0167
PAN SEQ NO: 03
ICC

SALE AMOUNT
TOTAL £1,425.36

PIN VERIFIED
PLEASE RETAIN FOR YOUR RECORDS
Thank You

04/04/25 09:23
AUTH CODE: R94107

CUSTOMER COPY
PLEASE RETAIN RECEIPT

Handy Group Ltd
School Lane
Chandlers Ford Industrial Estate
Eastleigh
Hampshire
SO53 4DG
Tel: 02380 481100
Fax: 02380 573025

Warranty Claim Branch: NS

CASH SALE INVOICE

Customer Name & Address:
Mr. D Burgess
12 Malvern Gardens
Totter
Southampton
Hampshire
SO40 8EX

Preferred Contact No: 07955244363
Served by: Kerrie Dunkley
Branch: School Lane
Telephone: 02380579800

Page 1
Time 09:25

Order Number	Date & Tax Point	Created By	Created Date
123456789	04/04/2025	Lee-V Edridge	13/03/2025

Make & Model	Chassis No.	Engine No.	Mileage In	Mileage Out
Ford Chausson Titanium 640 Aut	YNF8	13218	13218	

Reg No.	Reg Date	Vehicle No.	Carriage	Route	WLP No.	Job No.
DB06GET	14/05/2019	1723170			149025	120179

Description of Goods / Services	Qty	Unit Price	Unit	Net Total
A. LAB				
X F2631801 V-BELT	5.20	135.00		702.00
X F2344230 BOLT	1.00	86.35	86.35 EACH 15.00	73.40
X F2715824 COVER - TIMING BELT	1.00	2.06	2.06 EACH 10.00	1.86
X F2361304 V-BELT	1.00	146.83	146.83 EACH 15.00	124.81
X F2018353 V-BELT	1.00	33.70	33.70 EACH 10.00	29.33
X F2011524 BOLT - HEX HEAD	1.00	15.58	15.58 EACH 10.00	14.03
X F2808131 PAN ASSY - ENGINE OI	1.00	5.70	5.70 EACH 10.00	5.13
X F2007929 FILTER ASSY - OIL	1.00	35.31	35.31 EACH 10.00	31.78
X F2011555 DRIVE BELT - OIL PUM	1.00	17.96	17.96 EACH 10.00	16.17
X F2283198 TUBE ASSY - OIL PUMP	1.00	32.40	32.40 EACH 10.00	29.16
X F2633427 SEALANT - SILICONE	1.00	11.67	11.67 EACH 10.00	10.51
X OCAS030 FORD 0W30 ENGINE OIL	2.00	20.23	20.23 EACH 10.00	36.42
	110.00	1.20	1.20 EACH 15.00	112.20
Menu Subtotal:				1187.80

V	Rate	Service/Goods	VAT	Net	V.A.T.	Total	Paid	Owing
S	20.00	1187.80	237.56	1187.80	237.56	1425.36	1425.36	0.00

Bank Details: HSBC UK Bank PLC
Account Name: Handy Group Limited
Account Number: 40-42-18-03856188

Reg Office: School Lane, Chandlers Ford, Hampshire SO53 4DG
Registered in England No: 192872 VAT No: 08 568 7215 08

Habitation Service Reports

Habitation service info

Habitation service photos

Test drive

Test drive - 10 mins

Further details

Engine lights

Further info

Dashboard Ghosting / Mileage flashing

CMS MOTORHOME INSPECTION FORM

Sign off

Completed by	
Date/Time	
<p>In receiving this form you are automatically agreeing with this acknowledgment. Whilst it would be nice to have a full AA style report and professional habitation check, it is not realistic and we are not trained to do so, so take all descriptions & reports as the assessors opinion only. All of our listed checks were opinion of the assessor before the date of the auction, conditions of the motorhome or caravan are expected to change in that time. Take into consideration fair wear and tear for the age of the motorhome. We do not test heating, gas, electric, water systems or accessories. All motorhomes are driven to the auction unless stated. MOT history & mileage checks are public record for the buyer to do their basic due diligence with. This is a trade auction only and must be treated as such. Bidding is bound by British Car Auction terms and conditions. Please visit https://www.bca.co.uk for auction terms and conditions. Bid at your own risk.</p>	