

General Information

Make & Model	Elddis Prestige 125
Reg Number - NO GAP	YJ16BRV
HPI Clear	Yes
VAT	No
Engine Size	2.0
ВНР	130
Transmission	Manual
Miles or KM	Miles
Mileage	29585
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	
Engine Keys Count	
V5 present	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass



Mechanical Inspection

Brake Pedal Pressure Pass?	Yes
Handbrake Test Pass?	Yes
Static Gear Selection Pass?	Yes
Clutch Slip Test Pass?	Yes
Steering Noise	No
Engine noise	No

Test Drive

Test drive - 10 mins	Pass
Engine Lights	No
Engine Lights Info	
Dashboard Ghosting	No
Cruise Control Comment	



External Inspection

External Extras	Gaslow, Satellite dish, Reversing camera, Awning, Solar panel
Decals	Good
Decals Further Info	
Any Damage Found	Yes
Damage Further Info	Clip for rear tailgate broken // laquer peel on o/s rear corner panel // sat dish damaged on edge
Windscreen	No damage
Alloy Wheels	N/A
Alloy Wheels Further Info	
Tyres Illegal/Cracking/Out of Date	No
Tyre Further Info	
Damp Floor Underneath	No
Damp Further Info	
Electric Step	N/A
Self Levelling Work	N/A
Pop Top Canvas Damage	N/A



Internal Inspection

Internal Look Original	Yes
Berths	3
Belts	4
Bed Options	Transverse Island Bed
Lounge Layout	Half Dinette
Layout Correct	Yes
Further Comments	No
Further Comments Info	
Internal Extras	cab A/C, Upgraded stereo, Tv(s), Bluetooth, DAB radio, Cab blinds, Cruise control, Oven, Multifunction steering wheel, tracker
Other Extras	
Electrics Turn On	Yes
Control Panel Damaged	No
Stereo Turn On	Yes
Smell or Signs of Smoking	No
Cushions Correct	Yes
Boiler Present	Yes
Overhead Lockers Ready	Yes



Internal Damage & Damp Check

Internal Damage	No
Damp Visible/Soft	Yes
Damp Info	Very light Staining around the front skylight not reading// 77% in wall under kitchen // 33% and light stain in dinette wall behind drivers seat
Floor Damp/Spongy/Damaged	No
Manuals Present	Yes

Service History

Engine Service History	Partial
Service Info	
Cam Belt Changed	N/A
Habitation Service Reports	Partial
Habitation Info	
V5 Tested on DVLA	Yes
All Stages Completed	Yes
Completed By	Daryl
Sign-off Date	
Price Guide	



CMS MOTORHOME INSPECTION FORM - PHOTOS

External Damage Photos











Photo 4

Powered by fastfield Photo Page 1



CMS MOTORHOME INSPECTION FORM - PHOTOS

Damp Photos







Photo 1 Photo 2 Photo 3

Powered by fastfield Photo Page 2